

The licensee failed to effectively implement a program of steam generator inspections which:

- was founded upon and accounted for the known and likely potential degradation mechanisms that could be occurring
- was sensitive to and accounted for conditions that increased the susceptibility of tubes to these degradation mechanisms
- accounted and compensated for conditions that challenged or limited detection capabilities
- adjusted or modified inspection methods and analysis during the inspection process to account for anomalies and other new conditions encountered

All of the above to provide reasonable assurance of steam generator tube integrity.

Alsy

ITEM # 53