

8/11/77

DISTRIBUTION:

- Docket
- NRC PDR
- Local PDR
- ORB#3 Rdg
- EGCase
- WMcDonald
- KRGoller
- CParrish
- RClark
- OELD
- OI&E (3)
- BJones
- BScharf (10)
- DEisenhut
- ACRS (16)
- CMiles
- TBAbernathy
- JRBuchanan
- File

Docket No. 50-251

Florida Power & Light Company
 ATTN: Dr. Robert E. Uhrig
 Vice President
 P. O. Box 013100
 Miami, Florida 33101

Gentlemen:

On August 3, 1977, we issued an Order for Modification of License for Turkey Point Unit No. 4. Our Order amended Facility Operating License No. DPR-41 and permits continued operation of Turkey Point Unit No. 4 for six equivalent months of Cycle 4 operation. Our Order also contained other limitations for operation of Turkey Point Unit No. 4.

The August 3, 1977 Order contained a typographical error in Section III, Provision 3, and an error in Section III, Provision 4. Enclosed is a signed original of a Corrective Order which corrects the typographical error in Provision 3 and which corrects Provision 4 to reflect the content of our Safety Evaluation issued with our Order of August 3, 1977. A copy of the Corrective Order is being filed with the Office of the Federal Register for publication.

Sincerely,

151

George Lear, Chief
 Operating Reactors Branch #3
 Division of Operating Reactors

Enclosure:
 Corrective Order

cc w/enclosure:
 See next page

OFFICE >	ORB#3	ORB#3	OELD	AD/ORS	D/DR	DD/NRR
SURNAME >	RClark	GLear	Wassman	KRGoller	VStell	EGCase
DATE >	8/11/77	8/11/77	8/11/77	8/12/77	8/11/77	8/11/77

cc:

Mr. Jack R. Newman, Esquire
Lowenstein, Newman, Reis & Axelrad
1025 Connecticut Avenue, N. W.
Suite 1214
Washington, D. C. 20036

Environmental & Urban Affairs Library
Florida International University
Miami, Florida 33199

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

In the Matter of
FLORIDA POWER AND LIGHT COMPANY
Turkey Point Plant Unit No. 4

)
)
)
Docket No. 50-251

CORRECTIVE ORDER


On August 3, 1977, the Nuclear Regulatory Commission issued an Order for Modification of License in the captioned matter. Said Order contained two errors in Section III, Provision 3 and 4. This Corrective Order will rectify such error.

Accordingly, pursuant to the Atomic Energy Act of 1954, as amended, and the Commission's Rules and Regulations in 10 CFR Parts 2 and 50, IT IS ORDERED THAT Facility Operating License No. DPR-44 is hereby amended by revising provisions 3 and 4 of Section III of the Order for Modification of License, in the captioned matter, dated August 3, 1977, to read as follows:

3. The concentration of radioiodine in the primary coolant shall be limited to 1 microcurie/gram during normal operation and to 30 microcuries/gram during power transients as defined in the Safety Evaluation.
4. Reactor operation shall be terminated and Nuclear Regulatory Commission approval shall be obtained prior to resuming operation if primary to secondary leakage attributable to the

denting phenomena is detected in 2 or more tubes per plant during any 20 day period.

FOR THE NUCLEAR REGULATORY COMMISSION

A handwritten signature in black ink, appearing to read "Edson G. Case", written over the typed name.

Edson G. Case, Acting Director
Office of Nuclear Reactor Regulation

Dated in Bethesda, Maryland
this 11th day of August 1977.