

Posted

Collection to Ammt 119 to DPR-41

Docket Nos. 50-250
and 50-251

Mr. C. O. Woody
Group Vice President
Nuclear Energy
Florida Power and Light Company
P.O. Box 14000
Juno Beach, Florida 33408

Dear Mr. Woody:

DISTRIBUTION

Docket File
NRC & Local PDRs
PD22 Reading
S. Varga
G. Lainas
D. Miller
D. McDonald
OGC-Bethesda
D. Hagan
E. Jordan
J. Partlow

T. Barnhart (4)
Wanda Jones
E. Butcher
Tech Branch
ACRS (10)
GPA/PA
ARM/LFMB
Gray File

SUBJECT: ADMINISTRATIVE ERRORS - PREVIOUSLY ISSUED AMENDMENTS
FOR THE TURKEY POINT PLANT

On July 28, 1987, the Commission issued Amendment Nos. 125 and 119 to Facility Operating License Nos. DPR-31 and DPR-41 for Turkey Point Units 3 and 4, respectively. The amendments added Technical Specifications for the reactor vessel level monitoring system (RVLMS).

Table 3.5-5, Action Statements 8 and 9, did not correctly reference Special Report Specification 6.9.3(A). Enclosed are the corrected pages to be inserted in Appendix A of Facility Operating License Nos. DPR-31 and DPR-41, respectively.

In addition, Amendment Nos. 124 and 118, issued June 8, 1987 to Facility Operating License Nos. DPR-31 and DPR-41 for Turkey Point Units 3 and 4, respectively, also contained an administrative error. The instructions for inserting and removing the amendment pages should have specified the removal of page 3.8-2, which was deleted when Technical Specification 3.18-1 for the auxiliary feedwater system was added.

In summary, replace the pages of Table 3.5-5 containing the Action Statements with the enclosed corrected pages. In addition, remove page 3.8-2 from the Technical Specifications.

Sincerely,

Daniel G. McDonald, Project Manager
Project Directorate II-2
Division of Reactor Projects-I/II

Enclosures:
As stated

cc w/enclosures:
See next page

LA-PDII-2
DMcDonalder
9/16/87

PM:PDII-2
DMcDonald:bg
9/16/87

D:PDII-2
HBerlow
9/16/87

Mr. C. O. Woody
Florida Power and Light Company

Turkey Point Plant

cc:

Harold F. Reis, Esquire
Newman and Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

Administrator
Department of Environmental
Regulation
Power Plant Siting Section
State of Florida
2600 Blair Stone Road
Tallahassee, Florida 32301

Mr. Jack Shreve
Office of the Public Counsel
Room 4, Holland Building
Tallahassee, Florida 32304

Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street
Atlanta, Georgia 30323

Norman A. Coll, Esquire
Steel, Hector and Davis
4000 Southeast Financial
Center
Miami, Florida 33131-2398

Martin H. Hodder, Esquire
1131 NE, 86th Street
Miami, Florida 33138

Mr. C. M. Wethy, Vice President
Turkey Point Nuclear Plant
Florida Power and Light Company
P.O. Box 029100
Miami, Florida 33102

Joette Lorion
7269 SW, 54 Avenue
Miami, Florida 33143

Mr. M. R. Stierheim
County Manager of Metropolitan
Dade County
Miami, Florida 33130

Mr. Chris J. Baker, Plant Manager
Turkey Point Nuclear Plant
Florida Power and Light Company
P.O. Box 029100
Miami, Florida 33102

Resident Inspector
U.S. Nuclear Regulatory Commission
Turkey Point Nuclear Generating Station
Post Office Box 57-1185
Miami, Florida 33257-1185

Attorney General
Department of Legal Affairs
The Capitol
Tallahassee, Florida 32304

Jacob Daniel Nash
Office of Radiation Control
Department of Health and
Rehabilitative Services
1317 Winewood Blvd.
Tallahassee, Florida 32399-0700

Intergovernmental Coordination
and Review
Office of Planning & Budget
Executive Office of the Governor
The Capitol Building
Tallahassee, Florida 32301

TABLE 3.5-5 (Continued)

ACTION STATEMENTS

- ACTION 1 With the number of OPERABLE accident monitoring instrumentation channel(s) less than the Total Number of Channels shown in Table 3.5-5, either restore the inoperable channel(s) to OPERABLE status within 7 days, or be in a condition with $K_{eff} < 0.99$, % thermal power excluding decay heat equal to zero, and an average coolant temperature $T_{avg} < 350^{\circ}\text{F}$ within the next 12 hours.
- ACTION 2 With the number of OPERABLE accident monitoring instrumentation channels less than the minimum channels OPERABLE requirements of Table 3.5-5, either restore the inoperable channel(s) to OPERABLE status within 48 hours, or be in a condition with $K_{eff} < 0.99$, % thermal power excluding decay heat equal to zero, and an average coolant temperature $T_{avg} < 350^{\circ}\text{F}$ within the next 12 hours.
- ACTION 3 Operation may continue up to 30 days with less than minimum channels OPERABLE for narrow range instruments.
- ACTION 4 Or close the associated block valve and open its circuit breaker.
- ACTION 5 With the number of OPERABLE Channels less than required by the Minimum Channels OPERABLE requirements, initiate the preplanned alternate method of monitoring the appropriate parameter(s), within 72 hours, and:
- 1) either restore the inoperable channel(s) to OPERABLE status within 7 days of the event, or
 - 2) prepare and submit a Special Report to the Commission pursuant to Specification 6.9.3 within 30 days following the event outlining the action taken, the cause of the inoperability, and the plans and schedule for restoring the system to OPERABLE status.
- ACTION 6 With one hydrogen monitor inoperable, restore the inoperable monitor to OPERABLE status within 30 days or be in at least HOT SHUTDOWN within the next 6 hours.
- ACTION 7 With both hydrogen monitors inoperable, restore at least one monitor to OPERABLE status within 72 hours or be in at least HOT SHUTDOWN within the next 6 hours.
- ACTION 8 With the number of OPERABLE Channels one less than the Total Number of Channels restore the system to OPERABLE status within 7 days. If repairs are not feasible without shutting down, prepare and submit a Special Report to the commission pursuant to the specification 6.9.3(k) within 30 days following the event outlining the action taken, the cause of the inoperability and the plans and schedule for restoring the system to OPERABLE status.

TABLE 3.5-5 (Continued)

ACTION STATEMENTS

ACTION 9

With the number of OPERABLE Channels less than the Minimum Channels OPERABLE requirements, restore the inoperable channel(s) to OPERABLE status within 48 hours. If repairs are not feasible without shutting down:

1. Initiate an alternate method of monitoring the reactor vessel inventory; and
2. Prepare and submit a Special Report to the Commission pursuant to Specification 6.9.3(j) within 30 days following the event outlining the action taken, the cause of the inoperability and the plans and schedule for restoring the system to OPERABLE status; and
3. Restore at least one channel to OPERABLE status at the next scheduled refueling.