

TS - TRM (tech reqmt manual) under II

IP2 TS more stringent and detailed than others

- inspection freq.
- NRC restart approval
- addresses hourglassing
- NRC reporting (45 d, immediate if significant changes, significant hourglassing)

Still did not capture or prewarn IP2 condition in making

- denting and hourglassing was setting up for tube failure
- leakage TS not adequate to prevent small leaks from developing into bigger ones
- no requirement on data quality
- does not specify what should be reported in 45 d report

↑ Indent

TS or TRM should be strengthened

- current knowledge of degradation mechanisms
- technique and methods (qualification, data quality)
- leakage TS needs to be reassessed

NRC needs to reevaluate what information we want the licensee to report and what time frame

J/83

**Contractor support**

**Did not raise noise issue**

**missed several indications**

**integrated assessment of results - inadequate**