Page 1

From:<JCash@ramc.net>To:<clc@nrc.gov>, <single@state.wy.us>Date:1/4/02 4:20PMSubject:License SUA-1548

YO. SOL

As per license condition 12.1, please be noticed that a Wyoming DEQ reportable spill occurred at the Smith Ranch Facility on January 4, 2002. The spill occurred in Wellfield Three from well 3-P-163 when a galvanized fitting on the wellhead corroded through. The spill was approximately 1,800 gallons of production fluid containing about 18 ppm U(subscript: 3)O (subscript: 8). A written report which details the corrective action will follow.

If you have any questions I can be reached at 307-358-3744, ext. 62.

John W. Cash Manager EHS & Regulatory Affairs Rio Algom Mining LLC. Smith Ranch Facility

CC: <jhl@nrc.gov>, <BFerdinand@ramc.net>, <PGoranson@ramc.net>



Received: from igate.nrc.gov by nrcgwia.nrc.gov; Fri, 04 Jan 2002 16:19:53 -0500 Received: from nrc.gov by smtp-gateway ESMTPœ id QAA05498; Fri, 4 Jan 2002 16:17:27 -0500 (EST) From: JCash@ramc.net Subject: License SUA-1548 To: clc@nrc.gov, single@state.wy.us Cc: jhl@nrc.gov, BFerdinand@ramc.net, PGoranson@ramc.net Date: Fri, 4 Jan 2002 14:46:20 -0600 Message-ID: <OFA833250B.FC4B6343-ON86256B19.0078C51F@net> X-MIMETrack: Serialize by Router on CommServer/Server/RioAlgom(Release 5.0.5 ISeptember 22, 2000) at 01/04/2002 02:46:22 PM MIME-Version: 1.0 Content-type: text/plain; charset=us-ascii

As per license condition 12.1, please be noticed that a Wyoming DEQ reportable spill occurred at the Smith Ranch Facility on January 4, 2002. The spill occurred in Wellfield Three from well 3-P-163 when a galvanized fitting on the wellhead corroded through. The spill was approximately 1,800 gallons of production fluid containing about 18 ppm U(subscript: 3)O (subscript: 8). A written report which details the corrective action will follow.

If you have any questions I can be reached at 307-358-3744, ext. 62.

John W. Cash Manager EHS & Regulatory Affairs Rio Algom Mining LLC. Smith Ranch Facility