ML020950506.txt

LICENSEE: NORTHEAST UTILITIES

SITE: MILLSTONE 2 EN NUMBER: 27209

DOCKET: 05000336 EVENT DATE: 05-05-94

RX TYPE: PWR EVENT TIME: 15:35

VENDORS: CE NOTIFY DATE: 05-05-94

EMERGENCY CLASS: N/A REGION: 1 STATE: CT TIME: 15:46

OPS OFFICER: RUDY KARSCH

10 CFR SECTION: AIND 50.72(b)(2)(iii)(D) ACCIDENT MITIGATION UNIT SCRAM RX INIT INITIAL MODE CURR CURRENT MODE

CODE CRIT PWR PWR

2 N N O COLD SHUTDOWN O COLD SHUTDOWN

THE LICENSEE DISCOVERED A DESIGN DEFICIENCY IN UNDERVOLTAGE MODULES WHICH SHORTENS THEIR DESIGN LIFE.

UNDERVOLTAGE MODULES USED IN ACCIDENT MITIGATION EQUIPMENT WERE EXPECTED TO HAVE A DESIGN LIFE OF TWENTY YEARS, BUT THE LICENSEE HAS EXPERIENCED RANDOM FAILURES WHICH INDICATE A DESIGN LIFE OF 1.5 YEARS. INVESTIGATIONS BY THE LICENSEE REVEALED A DESIGN DEFICIENCY WHICH CONTRIBUTES TO ACCELERATED AGING. IF THREE OUT OF FOUR MODULES FAILED SIMULTANEOUSLY, ACTIONS TO MITIGATE ACCIDENT CONSEQUENCES MIGHT NOT OCCUR. THE LICENSEE HAS A PROGRAM IN PLACE TO REPLACE MODULES PERIODICALLY SO MODULES VARY IN AGE. THE LICENSEE FEELS THAT THIS REDUCES THE PROBABILITY THAT THREE MODULES WOULD FAIL SIMULTANEOUSLY. THE LICENSEE DOES NOT THINK THIS PROBLEM IS GENERIC TO OTHER CE PLANTS. THE LICENSEE INFORMED THE NRC RESIDENT INSPECTOR AND STATE AND LOCAL GOVERNMENT AGENCIES.