

**RELEASE TO PUBLISH UNCLASSIFIED NRC STAFF
SPEECHES, PAPERS, AND JOURNAL ARTICLES**
(Please type or print)

1. TITLE *(State in full as it appears on the speech, paper, or journal article)*
U.S. Operating Experience with Thermally Treated Alloy 600 Steam Generator Tubes

2. AUTHOR(s)
Kenneth J. Karwoski

3. NAME OF CONFERENCE, LOCATION, AND DATE(s)
**21st EPRI Steam Generator NDE Workshop
Berkeley, CA
July 15-17, 2002**


4. NAME OF PUBLICATION
Conference Proceedings

5. NAME AND ADDRESS OF THE PUBLISHER	TELEPHONE NUMBER OF THE PUBLISHER


YES	NO	6. PAGE CHARGES
<input checked="" type="checkbox"/>	<input type="checkbox"/>	If yes, attach a completed and signed NRC Form 30, "Request for Administrative Services." The NRC Form 30 must be transmitted for funding and an obligating document issued by ADM <u>before the paper is sent for publication</u> . <i>If an NRC Form 30 is not submitted, NRC may refuse to pay the page charges, and the author will become personally responsible.</i>

YES	NO	7. CERTIFICATION (ANSWER ALL QUESTIONS)	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	A. TECHNICAL AND POLICY REVIEWS	Speeches, papers, and journal articles require management and policy reviews of technical and policy issues per NRC MD 3.9, Part 1(A)(2). Please check the "YES" box to certify that the speech, paper, or journal article complies with this statement.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	B. COPYRIGHTED MATERIAL	Does this speech, paper, or journal article contain copyrighted material? If yes, attach a letter of release from the source that holds the copyright.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	C. PATENT CLEARANCE	Does this speech, paper, or journal article require patent clearance? If yes, the NRC Patent Counsel must signify clearance by signing below.
		NRC PATENT COUNSEL <i>(Type or Print Name)</i>	SIGNATURE
			DATE
<input checked="" type="checkbox"/>	<input type="checkbox"/>	D. REFERENCE AVAILABILITY	Is all material referenced in this speech, paper, or journal article available to the public either through a public library, the Government Printing Office, the National Technical Information Service, or the NRC Public Document Room? If no, list below the specific availability of each referenced document
		SPECIFIC AVAILABILITY	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	E. METRIC UNIT CONVERSION	Does this speech, paper, or journal article contain measurement and weight values? If yes, all must be converted to the International System of Units, followed by the English units in brackets, pursuant to the NRC Policy Statement implementing the Omnibus Trade and Competitiveness Act of 1988, Executive Order 12770, July 25, 1991.

8. RESPONSIBLE STAFF MEMBER

NAME <i>(Type or print name)</i> Kenneth J. Karwoski		OFFICE/DIVISION NRR/DE	MAIL STOP O-9H6
SIGNATURE 	DATE 7-3-02	TELEPHONE NUMBER 301-415-2752	E-MAIL I.D. kjk1@nrc.gov

9. AUTHORIZATION (Cannot be the same person listed in block 8.)

NRC OFFICIAL AUTHORIZING RELEASE <i>(Type or print name)</i> W.H. Bateman	
SIGNATURE 	DATE 7/3/02

U.S. OPERATING EXPERIENCE WITH THERMALLY TREATED ALLOY 600 STEAM GENERATOR TUBES




**EPRI Steam Generator NDE Workshop
July 15, 2002**

**Kenneth J. Karwoski (kjk1@nrc.gov)
U.S. Nuclear Regulatory Commission
(301) 415-2752**

BACKGROUND

- **Mill annealed Alloy 600 SG tubes susceptible to various forms of degradation**
- **31 plants have replaced SGs as of 07/01/02**
 - 1 600 MA; 8 600 TT; 22 690 TT
- **Thermal treatment of Alloy 600 improves microstructure**
- **Other design improvements**
 - Hydraulic expansion of tubes into tubesheet
 - Stainless steel tube support plates with quatrefoil holes
 - Stress relief of low row tubes

Installation of Steam Generators with Alloy 600 TT Tubes as a Function of Year



3

STEAM GENERATOR MODELS WITH ALLOY 600 TT TUBES

Plant	Date	Model	Number of SGs	Replacement
Braidwood 2	1988	D5	4	N
Byron 2	1987	D5	4	N
Callaway	1984	F	4	N
Catawba 2	1986	D5	4	N
Comanche Peak 2	1993	D5	4	N
Indian Point 2	2000	44F	4	Y
Millstone 3	1986	F	4	N
Point Beech 1	1984	44F	2	Y
Robinson 2	1984	44F	3	Y
Salem 1	1997	F	4	Y
Seabrook 1	1990	F	4	N
Surry 1	1981	51F	3	Y
Surry 2	1982	51F	3	Y
Turkey Point 3	1982	44F	3	Y
Turkey Point 4	1983	44F	3	Y
Vogtle 1	1987	F	4	N
Vogtle 2	1989	F	4	N
Wolf Creek 1	1985	F	4	N

4

OPERATING EXPERIENCE Forced Outages

- **Eight unplanned outages related to SG issues**

- **3 Leakers**
 - **Byron 2 (2002) - 75 gpd, secondary side foreign object**

 - **Byron 2 (1996) - 120 gpd, secondary side foreign object**

 - **Surry 2 (1986) - Shut down for another issue but addressed small SG leak – secondary side foreign object**

5

OPERATING EXPERIENCE Forced Outages (cont'd)

- **5 “non-leaker” outages - all attributed to loose parts identified through loose part monitoring systems**
 - **3 outages due to Control Rod Guide Tube Support Pin Nuts:**
 - **Wolf Creek (2002), Vogtle 1 (1996), Robinson 2 (1989)**
 - **Damaged tubesheet and tube ends on hot-leg side**

 - **Point Beach 1 (2000) - No loose part found**

 - **Robinson 2 (1994) - Shut down for another issue but addressed secondary side loose part**
 - **In previous outages, 2 nearby tubes had been plugged (may have been related to this loose part)**


6

OPERATING EXPERIENCE Inspection Results

- -281,000 Alloy 600 TT tubes in service
- Average age = 14.4 calendar years
- Results of SG tube inspections submitted to NRC
- Experience grouped by models
 - Model D5, Model F, and Replacement models (44F, 51F, and Salem Model F)
- Inspection scope and frequency varies
 - D5 – typically all 4 SGs examined
 - F – typically 2 of 4 SGs examined
 - Replacement – varies - inspect all SGs, skip cycles, 1 of 3 then 2 of 3, or 1 of 3 each outage


7

Percentage of Plugged Tubes by Model




8

Causes of Tube Plugging (12/31/01)



9

Number of Tubes Plugged Per Year



10

OPERATING EXPERIENCE Observations

- **Seabrook axial crack-like indications at tube supports**
- **Mechanical denting at tubes supports**
- **Wear at tube supports - only 18 tubes plugged (12 at one plant last year)**
- **Volumetric indications attributed to tube wear in interior of tube bundle is not well explained**

11

OPERATING EXPERIENCE Observations (cont'd)

- **Causal mechanism for tube obstructions that prevent the passage of a bobbin coil is not readily ascertainable from "outage reports"**
- **Tube stabilization may be necessary as a result of continued degradation of plugged tubes**
 - **Several plants have been evaluating**
- **Tubesheet anomalies – not expanded, under expanded (i.e., not full length), or over expanded may require more frequent examination or preventive plugging**

12

OPERATING EXPERIENCE Observations (cont'd)

- **Tube inspections before and/or after secondary side maintenance**
 - **Before:** may miss opportunity to detect loose parts left in SG
 - **After:** may not be able to conclusively determine if loose part was the cause of indication
- **Manufacturing anomalies**
 - **Comprehensive preservice inspection could establish a baseline for dispositioning “anomalous” signals**

13

OPERATING EXPERIENCE Tube Pulls

- **Seabrook - 2002**
- **Byron 2 – 1998**
 - **Removed portions of 3 tubes with circumferential indications at expansion transition**
 - **Manufacturing related indications**
- **Surry 1 – 1990**
 - **Removed portions of 2 tubes to examine indications near expansion transition**
 - **Manufacturing related indications**
- **Surry 1 – 1986**
 - **Removed portion of 1 tube to examine indications near uppermost tube support**
 - **No degradation**

14

Operating Experience Tube Pulls (cont'd)

- **Needed to:**
 - **Conclusively determine nature of “manufacturing related” eddy current signals which can’t be traced to baseline**
 - **Conclusively determine nature of indications being detected at a number of plants**
 - **Volumetric**
 - **Loose Part Wear in interior of bundle**
 - **Support plate wear and denting**
 - **Obstructions/Restrictions**
 - **Cracking**
- **Uncertainties in determining type of degradation should be accounted for in operational assessments**

15

CONCLUSIONS

- **Relatively good operating experience attributed to:**
 - **Thermal treatment**
 - **Hydraulic expansion**
 - **Quatrefoil tube support hole design**
 - **Stainless steel tube supports**
- **Although experience has been favorable, there is a continued need to monitor for tube degradation including cracking**
- **Better understanding of inspection results will be needed to determine appropriate intervals between inspections**

16