Form TI-1 Case Resolution

Case Status:	Open	Closed 🗸			
RCODE: 1401	RCODE: 1401				
Region: II					
OLD - Complete Name, Address, C	ontact, Phone Number:				
Robinson Phillips Coal Preparation Pineville, WV 24874					
NEW - Complete Name, Address, (Contact, Phone Number:				
Gauge transferred to:					
Omar Mining P.O. Box 338 Madison, WV 25130	• •.				
(304) 369-1217 (already registered in GLTS?)					
Agreement State Licensee? (Double Check)	Yes	No 🖌			
Moved to an Agreement State?	Yes	No 🖌			
Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other) Inspector spoke with John McNew, the RSO of a coal company in the Pineville area. Mr. McNew stated that Massey Energy had purchased the site, and the prep plant was torn down. Inspectors contacted Mary Thornsbury of the West Virginia DEP. Ms. Thornsbury stated that Robinson Phillips was a big operator in the 1980's, but most of the mines they operated were sold or shut down. Miss Thornsbury recalled that the mine in Pineville was sold to Massey Energy, was closed, and was put under the care of Lloyd Adams, an employee of Massey. The inspector contacted Lloyd Adams (304) 732-7920, who stated that the old Robinson Phillips mine was sold by Massey Energy to Rapoca Energy in the early 90's. The inspector called the Rapoco corporate office at (276) 669-3400 and spoke to Ken Stacey in Environmental Safety. Mr. Stacey recalled when the plant was purchased, but stated that the gauge was not there because it had been picked up by the vendor for repairs. The inspector contacted Scott Morrell of Preparation Controls (a local vendor representative) to confirm this. Scott Morrell confirmed that the gauge in question was removed from the Robinson Phillips plant on 6/22/1993 and taken to Omar Mining in Madison, WV (a registered GL?). Mr. Morrell stated that the NRC records were correct in showing that the gauge was installed in 1982(3). However, NRC records also show the installation of the same device in 1993(3), when they should reflect its transfer to Omar Mining in Swas an error in GLDB (i.e., the licensee did not possess two devices as shown in NRC records -instead, the second device entry in GLDB should have been a transfer of the initial device on 6/22/1993, not a new installation).					
Describe Communication with Registration Vendor: Contacted Scott Morrell, a local representative of the vendor who had records documenting the devices at Robinson Phillips Coal.					
Vendor Follow-up Action: N/A					
Final Action Taken: Forwarded all information gathered to the GLTS staff in HQ.					
Cause of Bad Address/Lesson Learned: Error in entry of a transfer in GLDB?					

Form TI-2: Device Information

RCODE	: 1401							
ID	Model Number	Serial Number	Isotope	Activity (mCi)	Sold Date	Vendor	Status (A or N)	Comments
	7062BP	15062	Cs-137	100	19823	Kay-Ray / Sensall, Inc.	A	
	7062BP	15062	Cs-137	100	19933	Kay-Ray / Sensali, Inc.	A	Same device - should have been transferred out to Omar Mining on 6/22/93, not reassigned to this GL.
· · · ·								
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	Status	Comments

Status Codes: A - Source accounted for N - Source not accounted for

RCODE: 1401 Licensee Name: Robinson Phillips Coal Preparation

Form TI-3: General Licensee Inspection Documentation

RCODE: 1401				
General Licensee Information:				
	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:			
Result	s of inspection: (check the appropriate boxes)			
	The general licensee of record is located at the address of record and			
	all GLD are accounted for			
	not all GLD are accounted for			
~	The general licensee of record is <u>not</u> located at the address of record, however GLD are being used under new ownership at the address of record and			
	all GLD are accounted for			
	not all GLD are accounted for			
	The general licensee of record is <u>not</u> located at the address of record, however they are using GLD at another location and			
	all GLD are accounted for			
	not all GLD are accounted for;			
	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for AN alternate purpose.			
	Other: (explain)			
Gauge	e Information:			
D	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:			

inspector:

N. Jeff Griffis Materials Licensing and Inspection, Branch 1

Approved By:

20th for Jay 2 Aleason 2/10/2003 Jay Henson, Chief

3

Completion Date:

RCODE: 1401 Licensee Name: Robinson Phillips Coal Preparation

2/3/2003