

U.S. Nuclear Regulatory Commission
Page 2
February 28, 2003

If you have questions regarding this issue, please call me
at (729) 256-2636.

Sincerely,

original signed by:

T. E. Abney
Manager of Licensing
and Industry Affairs

Enclosure

cc (Enclosure):

ATTN: Document Control Desk
Mail Stop OWFN, P1-35
Washington, D.C. 20555-0001

(Via NRC Electronic Distribution)

U.S. Nuclear Regulatory Commission
Region II
Sam Nunn Atlanta Federal Center
61 Forsyth Street, SW, Suite 23T85
Atlanta, Georgia 30303-3415

Mr. Stephen J. Cahill, Branch Chief
U.S. Nuclear Regulatory Commission
Region II
Sam Nunn Atlanta Federal Center
61 Forsyth Street, SW, Suite 23T85
Atlanta, Georgia 30303-8931

NRC Senior Resident Inspector
Browns Ferry Nuclear Plant
10833 Shaw Road
Athens, AL 35611-6970

Kahtan N. Jabbour, Senior Project Manager
U.S. Nuclear Regulatory Commission
(MS 08G9)
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852-2739

U.S. Nuclear Regulatory Commission
Page 2
February 28, 2003

Enclosure

cc (Enclosure):

A. S. Bhatnagar, PAB 1E-BFN
M. J. Burzynski, BR 4X-C
R. G. Jones, POB 2C-BFN
J. E. Maddox, LP 6A-C
D. C. Olcsvary, LP 6A-C
C. M. Root, PAB 1G-BFN
J. R. Rupert, LP 6A-C
K. W. Singer, LP 6A-C
E. J. Vigluicci, ET 11A-K
R. E. Wiggall, PEC 2A-BFN
NSRB Support, LP 5M-C
EDMS-K

s:lic/submit/subs/Unit 1 Regulatory Framework

ENCLOSURE

Table 1: Regulatory Issues

Open Commitments to Implement Actions

Bulletins:

79-02	Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts
79-12	Short Period Scrams At BWR Facilities
79-14	Seismic Analysis for As-Built Safety Related Piping Systems
80-06	Engineered Safety Feature Reset Controls
84-02	Failure of GE Type HFA Relays in Use in Class 1E Safety Systems
86-02	Static "O" Ring Differential Pressure Switches
88-07	Power Oscillation in Boiling Water Reactors
88-10	Nonconforming Molded-Case Circuit Breakers
93-03	Resolution of Issues Related to Reactor Vessel Water Level Instrumentation in BWRs
96-03	Potential Plugging of Emergency Core Cooling Suction Strainers by Debris in Boiling Water Reactors

Generic Letters:

82-33	Instrumentation to Follow the Course of an Accident - R.G. 1.97
83-08	Modification of Vacuum Breakers on Mark 1 Containments
83-28	Salem ATWS
88-11	Radiation Embrittlement of Reactor Vessel Materials and its Impact on Plant Operations
88-14	Instrument Air Supply System Problems Affecting Safety Related Equipment
89-06	Safety Parameter Display System
89-08	Erosion/Corrosion-Induced Pipe Wall Thinning
89-10	Safety-Related Motor-Operated Valve Testing and Surveillance
89-16	Installation of a Hardened Wetwell Vent
96-01	Testing of Safety-Related Logic Circuits
96-05	Periodic Verification of Design Basis Capability of Motor Operated Valves
98-01	Readiness of Computer Systems at Nuclear Power Plants

NUREG-0737 (TMI Action Plan) Action Items

I.D.1	Control Room Design Review
I.D.2	Safety Parameter Display Console
II.B.3	Post-Accident Sampling System
II.E.4.2.1 -4	Containment Isolation Dependability - Implement Diverse Isolation
II.F.1.2.C	Accident - Monitoring - Containment High Range Radiation
II.F.1.2.D	Accident - Monitoring - Containment Pressure
II.F.1.2.E	Accident - Monitoring - Containment Water Level
II.F.2.4	(Generic Letter 84-23) - Instrumentation for Detection of Inadequate Core Cooling
II.K.3.13	HPCI/RCIC Initiation Levels
II.K.3.18	ADS Actuation Modifications
II.K.3.28	Qualification of ADS Accumulators

Commitment to Provide Submittal

Bulletins:

90-01 Loss of Fill Oil in Rosemount Transmitters
93-02 Debris Plugging of Emergency Core Cooling Suction Strainers

Generic Letters:

87-02 Verification of Seismic Adequacy of Mechanical and Electrical
Equipment In Operating Reactors
88-20, S 4 Individual Plant Examination of External Events for Severe Accident
Vulnerabilities
92-04 Resolution of the Issues Related to Reactor Vessel Water Level
Instrumentation in BWRs
95-07 Pressure Locking and Thermal Binding of Safety-Related and Power-
Operated Gate Valves
96-06 Assurance of Equipment Operability and Containment Integrity During
Design Basis Accident Conditions
97-04 Assurance of Sufficient Net Positive Suction for Emergency Core
Cooling and Containment Heat Removal Pumps
98-04 Potential for Degradation of the Emergency Core Cooling System and the
Containment Spray System After a Loss of Coolant Accident Because of
Construction and Protective Coating Deficiencies and Foreign Material
in Containment

Requirement for Submittal Within a Specified Period After Actions are Complete

Bulletins:

88-03 Inadequate Latch Engagement in HFA Type Relays Manufactured by GE
88-04 Potential Safety Related Pump Loss
95-02 Unexpected Clogging of a RHR Pump Strainer While Operating in
Suppression Pool Cooling Mode

Generic Letters:

88-01 NRC Position on IGSCC in BWR Austenitic Stainless Steel Piping
89-13 Service Water System Problems Affecting Safety Related Equipment
92-01 Reactor Vessel Structural Integrity
94-02 Long-Term Solutions and Upgrade of Interim Operating Recommendations
for Thermal-Hydraulic Instabilities in BWRs
94-03 Intergranular Stress Corrosion Cracking of Core Shrouds in BWRs