

(5-2002)
10 CFR 2.201**Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE

CIS-US, Incorporated

REPORT NUMBER(S) 2003-001

2. NRC/REGIONAL OFFICE

**Region I
475 Allendale Road
King of Prussia, PA 19406-1415**

3. DOCKET NUMBER(S)

99-0120

4. LICENSE NUMBER(S)

MA 20-9734

5. DATE(S) OF INSPECTION

March 17, 2003

6. INSPECTION PROCEDURES USED

87110

7. INSPECTION FOCUS AREAS

02.02, 02.07, 02.09, 02.10, 02.11, 02.14, 02.18, 02.20

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)

3225

2. PRIORITY

5

3. LICENSEE CONTACT

Paul Tyree

4. TELEPHONE NUMBER

781-275-7120 ext. 3020

☐

Main Office Inspection

Next Inspection Date: _____

☐

Field Office _____

☒

Temporary Job Site

Thomas Jefferson Hospital Blood Bank**PROGRAM SCOPE**

This inspection was limited to an on site inspection at a temporary job site in Philadelphia, PA. The licensee filed for reciprocity as required. The work performed consisted of electrical repairs to a CIS-US Model IBL 437C irradiator. The service representative had the following documents with him: NRC Form 3, a completed NRC Form 241, and a copy of 10 CFR Part 150, a copy of the CIS-US MA. License, most recent training certificate and a copy of the registration sheet for the CIS-US irradiator Model IBL 437C. The service representative has worked for CIS-US for five years. The individual also had a calibrated and operable survey instrument and film badge (Luxel). The individual did not have a copy of Parts 19 and 20. 10 CFR 150.20 (b) states, in part, that the licensee is subject to all applicable rules and regulations including Parts 19 which requires in 10 CFR Part 19 .11 that the licensee shall post current copies of the regulations in Part 19 and Part 20. This is a minor violation. The service representative indicated that he would acquire a copy of the required regulations.

