

Written Examination Review Worksheet

Q#	1. LOK (F/H)	2. LOD (1-5)	3. Psychometric Flaws					4. Job Content Flaws				5. Other		6. U/E/S	7. Explanation
			Stem Focus	Cues	T/F	Cred. Dist.	Partial	Job-Link	Minutia	#/units	Back-ward	Q=K/A	SRO Only		
1	F	3												S	
2	H	3											✓	E	Does not qualify as modified question. Stem has no significant modification. See ES-401D.2.f. <i>Resolution: Leave as is. Changed designation.</i>
3	H	2												S	
4	H	3												S	<i>Replaced question, because knowledge was duplicated in Question 78.</i>
5	H	3											✓	S	
6	F	2												S	
7	H	3											✓	S	
8	F	3												S	
9	H	3												S	
10	F	2	✓										✓	U	As worded, question does not adequately address a basis in an EOP. The stem gives the answer if one knows the setpoint. <i>Resolution: New question acceptable.</i>

Q#	1. LOK (F/H)	2. LOD (1-5)	3. Psychometric Flaws					4. Job Content Flaws				5. Other		6. U/E/S	7. Explanation	
			Stem Focus	Cues	T/F	Cred. Dist.	Partial	Job-Link	Minutia	#/units	Backward	Q=K/A	SRO Only			
67	H	3											✓		S	
68	H	4													S	
69	H	4				✓									U	Reference does not support answer. It state that a control rod insert block will be generated if there are more than two insert errors. The stem only discussed two insert errors. Also, it is not clear what is meant in Distractor B. <i>Resolution: Changed answer to B.</i>
70	F	3	✓												E	The reference indicates that the SYNC PERMIT light is only illuminated momentarily. The stem could be construed to read that it remains illuminated. <i>Resolution: Changed stem to indicate momentary illumination.</i>
71	H	3													S	
72	H	4											✓		S	
73	H	2													S	
74	H	3													S	
75	F	3											✓		S	
76	H	3													S	
77	F	3											✓		S	
78	F	3													U	The same knowledge is tested as in Question 4. <i>Resolution: Changed Question 4.</i>
79	F	3													S	
80	H	3													S	
81	F	2													S	
82	H	4	✓										✓		E	The stem does not give the status of any of the fans. Whereas, the reactor building pressure is being maintained at -1 inch of water and stable, it is not apparent why one would start standby gas treatment. <i>Resolution: Changed stem to indicate momentary illumination.</i>
83	H	3													S	
84	F	3													S	
85	H	3											✓		S	
86	H	3													S	
87	F	2											✓		S	

