April 4, 2003

U. S. Nuclear Regulatory CommissionAttn: Document Control DeskMail Stop P1-137Washington, DC 20555-0001



ULNRC04833

UE Ladies & Gentlemen:

DOCKET NUMBER 50-483
UNION ELECTRIC CO.
CALLAWAY PLANT UNIT 1
FACILITY OPERATING LICENSE NPF-30
MONTHLY OPERATING REPORT
MARCH/2003

The enclosed Monthly Operating Report for March/2003 is submitted pursuant to Section 5.6.4 of the Callaway Unit 1 Technical Specifications.

Warren A. Witt

Manager, Callaway Plant

Wanen A. with

WAW/JER/slk

Enclosure

JEZY

ULNRC04833 April 4, 2003

Page 2

cc: Mr. Ellis W. Merschoff
Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-4005

Senior Resident Inspector Callaway Resident Office U.S. Nuclear Regulatory Commission 8201 NRC Road Steedman, MO 65077

Mr. Jack Donohew (2 copies)
Licensing Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop 7E1
Washington, DC 20555-2738

Manager, Electric Department Missouri Public Service Commission PO Box 360 Jefferson City, MO 65102 Enclosure ULNRC04833 April 4, 2003

DOCKET NO.:

50-483

UNIT NAME:

CALLAWAY UNIT 1

COMPLETED BY:

J. E. Ready

TELEPHONE:

573/676-8617

FAX:

573/676-4202

REPORTING PERIOD:

MARCH/2003

1. DESIGN ELECTRICAL RATING (MWe-Net): 1171

2. MAX. DEPEND. CAPACITY (MWe-Net): 1125

		THIS MONTH	YR TO DATE	CUMULATIVE
3.	NUMBER OF HOURS REACTOR WAS CRITICAL	513	1,929	143,446
4.	HOURS GENERATOR ON-LINE	510	1,926	141,522
5.	REACTOR RESERVE SHUTDOWN HOURS	0.0	0.0	0.0
6.	NET ELECTRICAL ENERGY GENERATED (MWH)	584,814	2,242,524	155,786,620

Enclosure ULNRC04833 April 4, 2003

UNIT SHUTDOWNS

DOCKET NO .:

50-483

UNIT NAME:

CALLAWAY UNIT 1

COMPLETED BY: TELEPHONE:

J. E. Ready 573/676-8617

FAX:

573/676-4202

REPORT:MARCH/2003

TYPE METHOD OF CORRECTIVE F: FORCED **DURATION** SHUTTING DOWN **ACTIONS/** NO. S: SCHEDULED (HOURS) **REASON** THE REACTOR **COMMENTS** DATE 301 03-22-03 S 234 В

SUMMARY The Callaway Plant was shut down on March 22, 2003 to replace a Pressurizer Safety Valve, that was experiencing leakage past the seat.

REASON

- A: EQUIPMENT FAILURE (EXPLAIN)
- **B: MAINT. OR TEST**
- C: REFUELING
- D: REGULATORY RESTRICTION
- E: OPERATOR TRAINING / LICENSE EXAMINATION
- F: ADMINISTRATIVE
- G: OPERATIONAL ERROR (EXPLAIN)
- H: OTHER (EXPLAIN)

METHOD

- 1: MANUAL
- 2: MANUAL SCRAM
- 3: AUTOMATIC SCRAM
- 4. CONTINUATION
- 5: OTHER (EXPLAIN)