



Department of Energy
 Yucca Mountain Site Characterization
 Project Office
 P. O. Box 98608
 Las Vegas, NV 89193-8608

WBS 1.2.9.3

MAR 27 1992

Julie A. Canepa
 Acting Technical Project Officer
 for Yucca Mountain
 Site Characterization Project
 Los Alamos National Laboratory
 University of California
 N-5, Mail Stop J521
 P.O. Box 1663
 Los Alamos, NM 87545

VERIFICATION OF CORRECTIVE ACTION AND CLOSURE OF CORRECTIVE ACTION REQUEST
 (CAR) YM-92-003 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION
 (YMQAD) AUDIT YMP-92-01 OF LOS ALAMOS NATIONAL LABORATORY

The YMQAD staff has verified the corrective action to CAR YM-92-003 and determined the results to be satisfactory. As a result, the CAR is considered closed.

If you have any questions, please contact either Robert B. Constable at (702) 794-7945 or FTS 544-7945, or John S. Martin at (702) 794-7881 or FTS 544-7881.

R. E. Spence

Richard E. Spence, Director
 Yucca Mountain Quality Assurance Division

YMQAD:RBC-2658

Enclosure:
 CAR YM-92-003

cc w/encl:

- ~~K. R. Hooks, NRC, Washington, DC~~
- S. W. Zimmerman, NWPO, Carson City, NV
- S. L. Bolivar, LANL, Los Alamos, NM
- M. J. Clevenger, LANL, Los Alamos, NM
- J. L. Day, LATA, Los Alamos, NM

cc w/o encl:

- J. B. Tillman, LAAO
- J. W. Hines, OOD, AL
- A. R. Chernoff, MSD, AL
- J. W. Gilray, NRC, Las Vegas, NV
- N. J. Brogan, SAIC, Las Vegas, NV, 517/T-12

Add: K. R. Hooks

NH03

11

102.7

WM-11

070069

9204070345 920327
 PDR WASTE
 WM-11

PDR

**OFFICE OF CIVILIAN
RADIOACTIVE WASTE MANAGEMENT
U.S. DEPARTMENT OF ENERGY
WASHINGTON, D.C.**

14CAR NO.: YM-92-003
 DATE: 10/09/91
 SHEET: 1 OF 1
 QA
 WBS No.: 1.2.9.3

CORRECTIVE ACTION REQUEST

1 Controlling Document
TWS-QAS-QP-12.1, Rev. 4

2 Related Report No.
Audit YMP-92-01

3 Responsible Organization
Los Alamos Nat'l. Lab.

4 Discussed With
S. Bolivar

10 Response Due
20 days from issue

11 Responsibility for Corrective Action
R. Herbst

12 Stop Work Order Y or N
No

5 Requirement:
 TWS-QS-QP-12.1, Rev. 4, Para. 6.3, states in part, "...Instruments are calibrated by LANL's Standards and Calibration Group, by a service organization or by the operator. Individuals who perform calibrations...use written procedures."

6 Adverse Condition:
 Contrary to the above, the Laboratory has performed calibrations to memos/draft procedures.

DISCUSSION
 Examples include use of Memo No. TWS-EES-13-11-90-002 to perform calibrations for standards nos. 4526, 4527, and 4528. In addition, the automated digital electron microscope (ADEM) No. PN 840982 was calibrated utilizing a draft procedure. (Reference draft TWS-EES-DP-129).

7 Recommended Action(s):

1. Correct the deficiencies identified.
2. Investigate to determine if there are other similar deficiencies.
3. Take action to preclude recurrence.

8 Initiator J.S. Martin Date: 10/4/91

9 Severity Level -
 1 2 3

13 Approved By: R.C. Spence Date: 10/15/91
 OQA

15 Verification of Corrective Action:
*See verification of corrective action for CAR YM 92-003
 R 3-24-92*

16 Corrective Action Completed and Accepted:
 OQA [Signature] Date 3-24-92

17 Closure Approved By:
 OQA R.C. Spence 5/26/92

OFFICE OF CIVILIAN
RADIOACTIVE WASTE MANAGEMENT
U.S. DEPARTMENT OF ENERGY
WASHINGTON, D.C.

CAR NO. _____
DATE: _____
SHEET: _____ OF _____

CORRECTIVE ACTION REQUEST
(continuation sheet)

CORRECTIVE ACTION RESPONSE FOR CAR NO. YM-92-003:

Page 1 of 2

A. Extent of Deficiency:

The LANL YMP Quality Assurance Project Leader (QAPL) issued memo TWS-EES-13-10-91-047 requesting Principal Investigators (PIs) to determine if there are known instances not previously identified, where work is being conducted to draft procedures.

It has been determined that there are no other instances.

B. Root Cause:

For the first example cited, memo TWS-EES-13-11-90-002 was written to document how mass standard calibrations are conducted. It is not used to conduct the mass standard calibrations. The root cause of this condition is the calibration group's procedure is not adequate to meet LANL YMP requirements for calibrations.

The second example cites the automated electron microscope (ADEM) No. PN 840982 being calibrated to an "in-progress" procedure (TWS-EES-DP-129), this adverse condition was caused by the operator/calibrator's misunderstanding regarding proper procedure reference. The operator/calibrator made an incorrect entry of TWS-EES-DP-129 on the M&TE Calibration Record and consequently entered "in-progress" on "OPERATOR TO CALIBRATE" label found on the ADEM. The "in-progress" entry refers to DP-129, which currently is in review. The "OPERATOR TO CALIBRATE" label should have referenced the ADEM operator's manual directly. It was determined that there was no work done to the draft procedure and that the calibration was done according to the ADEM operator's manual.

C. Remedial Action:

Implementation of the remedial actions will be the responsibility of the LANL YMP QAPL. Scheduled completion date: February 28, 1992.

For the first example cited, procedure LANL-YMP-DP-609 is being written to document how mass standard calibrations are conducted.

For the second example cited, the operator/calibrator has replaced the "OPERATOR TO CALIBRATE" label with one referencing the ADEM operator's manual. The M&TE Calibration Record will be corrected to reference the ADEM operator's manual.

D. Corrective Action to Prevent Recurrence:

Implementation of the corrective action to prevent recurrence will be the responsibility of the LANL YMP QAPL. Scheduled completion date: February 28, 1992.

Let's dtd 11/8/91 - TWS-EES-13-11-91-032

OFFICE OF CIVILIAN
RADIOACTIVE WASTE MANAGEMENT
U.S. DEPARTMENT OF ENERGY
WASHINGTON, D.C.

CAR NO. _____
DATE: _____
SHEET: _____ OF _____

CORRECTIVE ACTION REQUEST
(continuation sheet)

CORRECTIVE ACTION RESPONSE FOR CAR NO. YM-92-003: (cont.)

Page 2 of 2

As a result of this CAR, the operator/calibrator now understands how to reference procedures on M&TE calibration records and labels.

Memo TWS-EES-13-10-91-047 has been distributed to all LANL YMP personnel. This memo instructed personnel to stop work on any work activity being conducted to draft procedures. The memo also states that LANL YMP personnel are NOT allowed to work to draft procedures. Therefore, mass standard calibrations will not be conducted until LANL-YMP-DP-609 is issued.

Response Approved	<u>S.L. Bolivar</u> LANL QAFL S.L. Bolivar	<u>11/2/91</u> DATE
Response Approved	<u>R. J. Herbst</u> LANL TPO R. J. Herbst	<u>11/8/91</u> DATE
Response Approved	<u>[Signature]</u> QAR	<u>11/18/91</u> DATE
Response Approved	<u>[Signature]</u> YMQAD	<u>11/21/91</u> DATE