

### MODE HOLD RESOLUTION FORM

Condition Report No. CR 02-03668 Mode: 5

Assigned Group: PE

Assigned Owner: St. Clair, T.

Justification for Removal of Mode Hold - Include Discussion of Cause (Assigned Owner or Designee):

Chronic leakage problems at the casing-to-cover joints on RCP P36-1 and P36-2 (CA#2 and CA#3) are being resolved under CR 02-09674 CA#1 and CA#2 per ECR 02-805-00. CR 02-09674 also has a mode 5 restraint associated with it. Quantification of the leakage (if any) at P36-3 and P36-4 is to be completed during the startup from 13RFO per CA#4 and CA#5. Implementation of ECR 02-805-00 for pumps P36-3 and P36-4 will be performed under WO #02-007530-000 and WO #02-007529-000 respectively and are not being performed this outage. Since the mode 5 restraint issues are being tracked by CR 02-09674, the mode 5 restraint associated with CR 02-03668 may be lifted.

Reference Applicable Documentation:


W.O. # \_\_\_\_\_

Operability  
Justification # \_\_\_\_\_

EWR # ECR 02-805-00

Other CR 02-09674

 \_\_\_\_\_ 1 1/15/03  
Assigned Owner Signature Date

 \_\_\_\_\_ 1 2/13/03  
Operational Approval for Removal Date  
(OPS Superintendent / OPS SRO Designee)

MODE 2 for CA 4+5

A/11