

October 3, 2003

D. M. Jamil
Vice President
Catawba Nuclear Station
Duke Energy Corporation
4800 Concord Road
York, South Carolina 29745

SUBJECT: CATAWBA NUCLEAR STATION, UNIT 2 RE: SUMMARY OF NRC'S REVIEW
OF STEAM GENERATOR TUBE INSERVICE INSPECTION REPORT FOR THE
FALL 2001 OUTAGE (TAC NO. MB3037)

Dear Mr. Jamil:

By letters dated October 24, 2001, January 17 and November 21, 2002, Duke Energy Corporation (the licensee) submitted reports and provided additional information summarizing the steam generator tube inspections performed during the end of cycle 11 (Fall 2001) refueling outage in accordance with the Catawba Nuclear Station, Unit 2 technical specifications (TS). The Nuclear Regulatory Commission (NRC) staff has completed its review of the licensee's inservice inspection reports and concludes that the licensee has provided the information required by the TS and that no additional follow-up is required at this time. A copy of the NRC staff's Safety Evaluation is enclosed.

Sincerely,

/RA/

Robert E. Martin, Senior Project Manager, Section 1
Project Directorate II
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-414

Enclosure: As stated

cc w/encl: See next page

October 3, 2003

D. M. Jamil
Vice President
Catawba Nuclear Station
Duke Energy Corporation
4800 Concord Road
York, South Carolina 29745

SUBJECT: CATAWBA NUCLEAR STATION, UNIT 2 RE: SUMMARY OF NRC'S REVIEW
OF STEAM GENERATOR TUBE INSERVICE INSPECTION REPORT FOR THE
FALL 2001 OUTAGE (TAC NO. MB3037)

Dear Mr. Jamil:

By letters dated October 24, 2001, January 17 and November 21, 2002, Duke Energy Corporation (the licensee) submitted reports and provided additional information summarizing the steam generator tube inspections performed during the end of cycle 11 (Fall 2001) refueling outage in accordance with the Catawba Nuclear Station, Unit 2 technical specifications (TS). The Nuclear Regulatory Commission (NRC) staff has completed its review of the licensee's inservice inspection reports and concludes that the licensee has provided the information required by the TS and that no additional follow-up is required at this time. A copy of the NRC staff's Safety Evaluation is enclosed.

Sincerely,

/RA/

Robert E. Martin, Senior Project Manager, Section 1
Project Directorate II
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

DISTRIBUTION:

PUBLIC	ACRS	JNakoski	MMurphy
PDII-1 R/F	OGC	EHackett	MLesser
WBeckner	GHill(4)	RMartin	
RHaag, RII	CHawes	CKhan	

Docket No. 50-414

Enclosure: As stated

cc w/encl: See next page

ADAMS Accession No. ML032790452

OFFICE	PDII-1/PM	PDII-1/LA	PDII-1/SC
NAME	RMartin	CHawes	JNakoski
DATE	10/6/03	10/6/03	10/6/03

OFFICIAL RECORD COPY

SAFETY EVALUATION BY THE OFFICE OF NUCLEAR REACTOR REGULATION
RELATED TO EVALUATION OF STEAM GENERATOR TUBE INSPECTION REPORT

DUKE ENERGY CORPORATION, ET AL

CATAWBA NUCLEAR STATION, UNIT 2

DOCKET NO. 50-414

By letters dated October 24, 2001, and January 17, 2002, Duke Power (Duke), the licensee for the Catawba Nuclear Station, Unit 2, submitted reports summarizing the steam generator tube inspections performed during the End of Cycle (EOC) 11 (Fall 2001) refueling outage. These reports were submitted in accordance with Catawba, Unit 2 technical specifications (TSs) sections 5.6.8.a. and 5.6.8.b. The Nuclear Regulatory Commission (NRC) staff developed a set of questions while reviewing these reports. Responses to these questions were submitted by the licensee in a letter dated November 21, 2002. A summary of the NRC's evaluation of the EOC 11 refueling outage inspection results is provided below.

Catawba Unit 2 has four Westinghouse Model D5 steam generators. The steam generators have full hydraulic expansion joints in the tubesheet and stainless steel tube support plates with quatrefoil holes. These steam generators were placed in service in 1986 and have thermally treated Alloy 600 tubing. According to the steam generator inspection summary reports, the licensee inspected between 1807 and 2210 tubes full length in each steam generator with a bobbin probe. In addition, the licensee inspected between 225 and 226 tubes partial length in each steam generator with a bobbin probe. The partial inspections were performed in the low row tubes and involved inspections from the tube end to the top support plate (the bobbin probe does not readily pass through the U-bend region due to the curvature of the bend). The licensee did not identify the inspections that were completed with specialized probes (e.g., rotating coil probes) in the summary reports. However, this information was provided in support of the conference call the NRC staff held with Duke during the Fall 2001 outage (See ADAMS Accession Number ML021780129 for a summary). The NRC staff requests that the licensee identify all probes (bobbin, rotating coil, etc.) used during inspections in future summary reports, including the extent of the inspections and the quantity of tubes inspected to aid the NRC staff in understanding the full extent of the inspections. As a result of these inspections no tubes were plugged.

The TSs also require the licensee to identify the location and percent of wall-thickness penetration for each indication of an imperfection. An imperfection is defined in the TSs (5.5.9.4.a.1) as an exception to the dimensions, finish or contour of a tube from that required by fabrication drawings or specifications. The licensee provided a listing of every tube (more than 5000) containing an imperfection. Due to the large number of tubes on the list and due to the multiple three letter codes associated with each tube, the NRC staff found it difficult to determine, based on this listing, what type of imperfections were being found and left in-service. In response to NRC questions, the licensee provided a discussion on this subject. Some of the imperfections being seen and left in-service are dents, wear marks and manufacturing buff

marks (MBMs). The licensee indicated that all dents were caused by manufacturing activities and that none of the dents are corrosion induced dents (i.e., service-induced). The licensee's report identified multiple "VOL" (volumetric) indications that were left in-service. In response to a NRC question, the licensee indicated that "VOL" would be a signal indicative of volumetric imperfections such as MBMs, intergranular attack (IGA) and wear. The licensee also stated that the site-specific eddy current guidelines indicate that "VOL" calls are below the plugging limit. The NRC staff questioned whether it would be appropriate to use the VOL code for IGA indications since industry has historically had difficulty reliably depth-sizing IGA. However, the NRC staff does not see this as a significant issue at this time because the licensee indicated that IGA has not yet been identified in the Catawba, Unit 2 steam generators. The licensee has identified wear marks at the tube-to-antivibration bar intersections and these are left in-service if their depth does not exceed the TS plugging limit (i.e., 40 percent throughwall). In addition, the licensee occasionally identifies wear from foreign objects. The licensee stated that manufacturing burnish marks are routinely observed and left in-service. In future summary reports, the NRC staff would find it beneficial if the licensee provided a summary of the types of imperfections being seen and left in-service in addition to the individual tube listing, since the individual tube listing does not make this clear in all cases (e.g., the use of "VOL" for multiple types of imperfections).

Based on review of the information provided by the licensee, the NRC staff concludes that the information the licensee was required to submit by their TSs was provided and that no additional follow-up is required at this time. However, the NRC staff made two observations as follows:

- In future summary reports, the NRC staff requests the licensee to identify all probes (bobbin, rotating coil, etc.) used during inspections, the extent of the inspections and the quantity of tubes inspected to aid the NRC staff in understanding the full extent of inspections.
- In future summary reports, the NRC staff would find it beneficial if the licensee provided a summary of the types of imperfections being seen and left in service in addition to the individual tube listing, since the individual tube listing does not make this clear in all cases (e.g., the use of "VOL" for multiple types of imperfections).

Principal Contributor: C. B. Khan, EMCB/DE

Date: October 6, 2003

Catawba Nuclear Station

cc:

Mr. Gary Gilbert
Regulatory Compliance Manager
Duke Energy Corporation
4800 Concord Road
York, South Carolina 29745

Ms. Lisa F. Vaughn
Duke Energy Corporation
Mail Code - PB05E
422 South Church Street
P.O. Box 1244
Charlotte, North Carolina 28201-1244

Anne Cottingham, Esquire
Winston and Strawn
1400 L Street, NW
Washington, DC 20005

North Carolina Municipal Power
Agency Number 1
1427 Meadowood Boulevard
P. O. Box 29513
Raleigh, North Carolina 27626

County Manager of York County
York County Courthouse
York, South Carolina 29745

Piedmont Municipal Power Agency
121 Village Drive
Greer, South Carolina 29651

Ms. Karen E. Long
Assistant Attorney General
North Carolina Department of Justice
P. O. Box 629
Raleigh, North Carolina 27602

NCEM REP Program Manager
4713 Mail Service Center
Raleigh, NC 27699-4713

North Carolina Electric Membership
Corporation
P. O. Box 27306
Raleigh, North Carolina 27611

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
4830 Concord Road
York, South Carolina 29745

Henry Porter, Assistant Director
Division of Waste Management
Bureau of Land and Waste Management
Department of Health and Environmental
Control
2600 Bull Street
Columbia, South Carolina 29201-1708

Mr. C. Jeffrey Thomas
Manager - Nuclear Regulatory
Licensing
Duke Energy Corporation
526 South Church Street
Charlotte, North Carolina 28201-1006

Saluda River Electric
P. O. Box 929
Laurens, South Carolina 29360

Mr. Peter R. Harden, IV
VP-Customer Relations and Sales
Westinghouse Electric Company
6000 Fairview Road
12th Floor
Charlotte, North Carolina 28210

Catawba Nuclear Station

cc:

Mr. T. Richard Puryear
Owners Group (NCEMC)
Duke Energy Corporation
4800 Concord Road
York, South Carolina 29745

Richard M. Fry, Director
Division of Radiation Protection
North Carolina Department of
Environment, Health, and
Natural Resources
3825 Barrett Drive
Raleigh, North Carolina 27609-7721