

CORRECTED COPY - Letter date - (year only)



Palo Verde Nuclear
Generating Station

David M. Smith
Plant Manager

Tel: 623-393-6116
Fax: 623-393-6077
e-mail:
DSMITH10@apsc.com

10CFR50.73

Mail Station 7602
PO Box 52034
Phoenix, Arizona 85072-2034

192-01133-DMS/SAB/DGM/DFH

January 21, 2003

January 21, 2004

ATTN: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS) Unit 2
Docket No. STN 50-529
License No. NPF-51
Licensee Event Report 2003-003-00

Attached, please find Licensee Event Report (LER) 50-529/2003-003-00 that has been prepared and submitted pursuant to 10CFR50.73. The LER reports a condition where a Source Range Monitor was inoperable at the start of core reload while loading the first two fuel assemblies, following a refueling outage involving complete core offload.

In accordance with 10CFR50.4, a copy of this LER is being forwarded to the NRC Regional Office, NRC Region IV and the Resident Inspector. If you have questions regarding this submittal, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (623) 393-6492.

Arizona Public Service Company makes no commitments in this letter. The corrective actions described in this LER are not necessary to maintain compliance with regulations.

Sincerely,

DMS/SAB/DGM/DFH/kg

Attachment

cc: B. S. Mallett
N. L. Salgado
M. B. Fields

NRC Region IV Administrator
NRC Senior Resident Inspector for PVNGS
NRC NRR Project Manager

IE 22