

14. ¹⁹⁹⁵ leaky Bldg. roof leak = DER resolution problem
 Crusty
 - d. cut out on 1992 study
 - Sec Cert. is OK
 - PSAL description
 (closed)
 ... but, did they fix the roof?

13. System 52 "Buildings & Structures"
 1993 DER ⇒ Radwaste Overhead
 Rolling door (modification)

SK versus NSR
 MCM 6A
 ⇒ does not refer to - explicitly - doors/structures
 ∴ may not still be fixed

II/I implications
 18. ^{NSR} Modify Air Steam piping -
 logs not updated
 DCI not checked etc

several stages
 (1994)
 1. abandon piping/plbcs
 2. rest of modify cancell

[97-0045]
 DER
 c. closed

⇒ closure of Modifs w/ scope change
 ∴ calculation proves it out


walkway needs to be SK

15. Tornado Missile Door - new Admin Bldg; say how the door (to MCR) via NSR tunnel
 DER
 MCM 6A
 ⇒ don't become a "missile" B/17 Nb. door is safety rele

16. ESW FIRE Dampers

App R.

SAS 0



no DER

no battles;
do you have to
POSTULATE

early 1990s
event
room got
"hot"

X5339

??

17. (unterminated) drain line, (brued),
without a guard pipe

5. (a) Hot H₂O heater - side heat source for
Battery Room

DER
25-
297

... look @ these incomplete "DER's"

(suggests it's a licensing business issue -
battery is single failure

⇒ corrective action OK