

February 2, 2005

Mr. Christopher M. Crane, President
and Chief Executive Officer
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, Illinois 60555

SUBJECT: RESPONSE TO NUCLEAR REGULATORY COMMISSION (NRC) BULLETIN 2003-02, "LEAKAGE FROM REACTOR PRESSURE VESSEL LOWER HEAD PENETRATIONS AND REACTOR COOLANT PRESSURE BOUNDARY INTEGRITY," BYRON STATION, UNITS 1 AND 2 - (TAC NOS. MC0525 AND MC0526)

Dear Mr. Crane:

On August 21, 2003, the U.S. Nuclear Regulatory Commission (NRC) issued NRC Bulletin 2003-02, "Leakage from Reactor Pressure Vessel Lower Head Penetrations and Reactor Coolant Pressure Boundary Integrity," to the industry. This bulletin informed addressees that current methods of inspecting the reactor pressure vessel (RPV) lower heads may need to be supplemented with bare-metal visual inspections in order to detect reactor coolant pressure boundary leakage. The bulletin also requested these addressees to provide the NRC with information related to inspections that have been performed to verify the integrity of the RPV lower head penetrations.

The bulletin requested that addressees provide a description of the RPV lower head penetration inspection program that would be implemented at their respective plants during the next and subsequent refueling outages. This description was to include the extent of the inspection, the inspection methods to be used, the qualification standards for the inspection methods, the process used to resolve the source of findings of boric acid deposits or corrosion, the inspection documentation to be generated, and the basis for concluding that their plant satisfied applicable regulatory requirements related to the structural and leakage integrity of the RPV lower head penetrations.

By letter dated September 22, 2003, (ML032691399), Exelon Generation Company, LLC (Exelon) provided its response to this request. Exelon committed to perform a bare-metal visual examination of the RPV lower head and 100 percent of the 58 RPV lower head penetrations, during the Fall 2003 and Spring 2004 refueling outages at Byron Station (Byron), Units 1 and 2, respectively. In its same response, Exelon indicated that the extent and frequency of subsequent visual examinations of the RPV lower head penetrations, beyond the Fall 2003 and Spring 2004 refueling outages, will depend upon the appropriate NRC and Industry guidance as well as the standardized EGC Procedure ER-AP-331-1001, "Boric Acid Corrosion Control (BACC) Inspection Locations, Implementation, and Inspection Guidelines." The NRC staff notes that there are a number of ongoing industry and NRC staff activities related to developing criteria for RPV lower head penetration inspections. The NRC staff expect that the criteria for these inspections will involve periodic bare-metal visual examinations or their equivalent.

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, the extent of the inspection and the methods used, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits and any corrective actions taken as a result of indications found.

By letter dated December 12, 2003, (ML033510558), Exelon provided a summary of its inspection results at Byron, Unit 1. Exelon reported it had performed a 360-degree bare-metal visual examination on all 58 RPV lower head penetrations. Exelon did not observe any evidence of RPV lower head penetration leakage.

By letter dated June 2, 2004, (ML041730450) Exelon provided a summary of its inspection results at Byron, Unit 2. Exelon reported it had performed a 360-degree bare-metal visual examination on all 58 RPV lower head penetrations. Exelon did not observe any evidence of RPV lower head penetration leakage.

Based on its review of Exelon's responses to NRC Bulletin 2003-02, the NRC staff finds that Exelon has met the reporting requirements of the bulletin for Byron. Accordingly, TAC Nos. MC0525 and MC0526 are closed for Byron, Units 1 and 2, respectively.

Sincerely,

/RA/

George F. Dick, Senior Project Manager, Section 2
Project Directorate III
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454 and STN 50-455

cc: See next page

C. Crane

-2-

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, the extent of the inspection and the methods used, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits and any corrective actions taken as a result of indications found.

By letter dated December 12, 2003, (ML033510558), Exelon provided a summary of its inspection results at Byron, Unit 1. Exelon reported it had performed a 360-degree bare-metal visual examination on all 58 RPV lower head penetrations. Exelon did not observe any evidence of RPV lower head penetration leakage.

By letter dated June 2, 2004, (ML041730450) Exelon provided a summary of its inspection results at Byron, Unit 2. Exelon reported it had performed a 360-degree bare-metal visual examination on all 58 RPV lower head penetrations. Exelon did not observe any evidence of RPV lower head penetration leakage.

Based on its review of Exelon's responses to NRC Bulletin 2003-02, the NRC staff finds that Exelon has met the reporting requirements of the bulletin for Byron. Accordingly, TAC Nos. MC0525 and MC0526 are closed for Byron, Units 1 and 2, respectively.

Sincerely,

/RA/

George F. Dick, Senior Project Manager, Section 2
Project Directorate III
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454 and STN 50-455

cc: See next page

Distribution:

PUBLIC	SMonarque	RGramm	OGC
GDick	LMarsh	JNakoski	
PDIII-2 RF	GCherukenki	ESullivan	

ADAMS ACCESSION NUMBER: ML043570039

OFFICE	PDIII-2/PM	PDII-2/LA	LPM	EMCB	PDII-2/SC
NAME	GDick	PCoates	SMonarque	ESullivan	GSuh
DATE	1/25/05	1/26/05	1/31/05	1/31/05	2/2/05

OFFICIAL RECORD COPY

Byron Station Units 1 and 2

cc:

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
801 Warrenville Road
Lisle, IL 60532-4351

Illinois Emergency Management
Agency
Division of Disaster Assistance &
Preparedness
110 East Adams Street
Springfield, IL 62701-1109

Document Control Desk - Licensing
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Mr. Dwain W. Alexander, Project Manager
Westinghouse Electric Corporation
Energy Systems Business Unit
Post Office Box 355
Pittsburgh, PA 15230

Joseph Gallo
Gallo & Ross
1025 Connecticut Ave., NW, Suite 1014
Washington, DC 20036

Howard A. Learner
Environmental Law and Policy
Center of the Midwest
35 East Wacker Drive
Suite 1300
Chicago, IL 60601-2110

U.S. Nuclear Regulatory Commission
Byron Resident Inspectors Office
4448 North German Church Road
Byron, IL 61010-9750

Ms. Lorraine Creek
RR 1, Box 182
Manteno, IL 60950

Chairman, Ogle County Board
Post Office Box 357
Oregon, IL 61061

Mrs. Phillip B. Johnson
1907 Stratford Lane
Rockford, IL 61107

Attorney General
500 S. Second Street
Springfield, IL 62701

Byron Station Plant Manager
Exelon Generation Company, LLC
4450 N. German Church Road
Byron, IL 61010-9794

Site Vice President - Byron
Exelon Generation Company, LLC
4450 N. German Church Road
Byron, IL 61010-9794

Senior Vice President - Nuclear Services
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Vice President of Operations - Mid-West
Pressurized Water Reactors
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Chairman
Will County Board of Supervisors
Will County Board Courthouse
Joliet, Illinois 60434

Director - Licensing and Regulatory Affairs
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Regulatory Assurance Manager - Byron
Exelon Generation Company, LLC
4450 N. German Church Road
Byron, IL 61010-9794

Associate General Counsel
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Vice President -
Licensing and Regulatory Affairs
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

Manager Licensing - Braidwood and Byron
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555