From:
 Ray Gallucci

 To:
 Phil Qualls

 Date:
 1/6/04 8:51AM

 Subject:
 Approved Exemptions/Deviations for III.G.2 OpManAx

I'm reviewing the FireDat database to try and find some examples of approved exemptions/deviations to help when I have to respond to the public comments that are coming in. (I'm about halfway through and have found only three, but I may not be focusing on the right words to indicate them.) You said you had identified at least 50. Do you have a list, or can you recreate? I assume only the ones approved for III.G.2 are relevant (I'm finding some in FireDat for other than III.G.2 as well). James, if you can help Phil in recreating the list, please do so.

:C:	James De	owns								
				·.				•		
		•	•	.`	· . · · ·	na in the second se		a	<b></b>	
										2
				•		С.,	د	· ,		۰ <u>.</u>
						; ;	:		•	1
						-, ,		1		
			-					• .		• •
		4 	. 1			• • •				
		7			٤	•		•••		
										÷., ì
		, <b>.</b> .					•	9 - - - -	1.	
					·					
,	· ·			•	•				•	•
					•				•	~
		· · · · · · · · · · · · · · · · · · ·			· · · · · ·	· · · · · · · · · · · · · · · · · · ·		1 1 		. P.3.

Page 1

			emption F	-		n	
Exem	ption #:  830329	0263 04	Approval Dat	03/14/19831	Verified:		
5033		SS PLANT Beaver Valley 1 The pipe tunnel lacks ar intervening combustible	automatic suppress	Quirements/Section SOURCE   pendix R   II.G. ion system and 20 fe components or alter	2.b. et of separation free	aof	 
	oanle 1 2 3 3 4 4 4 4 4 4 4 4 4 5 8 4 8 8 8 8 8 8 8 8	There is approximately foccurs; if such a loss do Because of the time ava assurance that one train recirculation coils.	es not occur these va ilable to take manual	alves would remain o	perable. p system, there is re	easonable	  }

.

.

•

•

			E	Exem	ption F	lecord In	put Scree	n		
Exemption #:	851206	0395 0	8	A	pproval Dat	11/19/1985	Verified:			
Docket Inform	Charles and the second s				STORES & LONG	uirements/Sectio				and in the second s
50364	WX	فيصفعك البروصي ويبين	392, J. M				SE(	CTION		
		<u> </u>	59 2, 0. 1	· · · ·	<u>Apr</u>	pendix R III.G	2.2			
		Ĭ			Reisian					
Description		multiple ho	t shorts.	minines () Versio (n. 1619	a tig	n i strate e c	t enclosed by 1-hour			
			· · · · ·	7 <b>9</b> - 1 - 19	the the second	10.000 10000000	a di senara di seconda di seconda Seconda di seconda di se Seconda di seconda di s		<b></b>	
Ratioanie		removing p control to t	ower fron he main c	n the transfo ontrol board	er relays and r d.	manual operation of	ndition can be mitigate of the effected relay th op detailed procedure	ereby shifting		
		for this fire	area cove	ering the ma	anual operator	actions required t	o regain control of on ower operated relief v	e main steam		
Add	Save	Delete	Clóne	GoTo	Exit	Search Screen	Correpondence Didate	Keyword Update		
		· · · · · · · · · · · · · · · · · · ·	· 、 · · ·		·····		1978 - A.	· · · · · · · · · · · · · · · · · · ·	<u>, , , , , , , , , , , , , , , , , , , </u>	
		·• :	•	·	en de pr	в.		9.		
			r	х хе х (		an a	$C_{\mu}$			

•1

•

Docket Information	SS PLANT Farley 2, J. M.	Requirements/Section In SOURCE	nformation SECTION	
Description:	Non-rad side corridor, auxiliary build enclosed.	ng, redundant train of cables n	ot 1-hour rated barrier	
Railoanle	The licensee committed to develop of manual operator actions required to pressurizer power operated relief va relief valves and block valves. The transoms have been certified by similar to that of the UL Class A crite	regain control of one main stea ves and the transfer relays for the vendor as being construct	m atmospheric relief valve, the the pressurizer power operated	
Add	Delete: Clone GoTo	xit Search Screen	Correpondence	
			,	

٠

Exemption	Record	Input	Screen
-----------	--------	-------	--------

Exemption #: 8608180061 Verified: Approval Dat 07/31/1986 124 Docket Information **Requirements/Section Information** DOCKET I NSSS I PLANT SOURCE 50461 GE Clinton 1 BTP 9.5-1 C.5.b.(2) Signa -50.00 Failure to meet separation criteria in eight fire areas Description · · · The second s ,.<sup>.</sup>. · • the care of the property we have seen as a construction of the property we fitted and a solu-We have a strategy of a strategy was a strategy of atloanle Associated circuits whose fire-induced spurious operation could affect shutdown were identified by a system review to determine those components whose spurious operation could affect shutdown. These spurious operations are to be prevented or terminated by operator actions which are to be contained in the plant emergency operating procedures. The staff concludes that the applicant has adequately addressed the effects of associated circuit interaction, and that the necessary isolation devices and the actions proposed in emergency Correpondence Exit Keyword Clone . Goto Add Save Delete Search Screen Update -----Update C Carling Street ÷ • 

	E	xemption F	Record Ing	out Screer	า	
Exemption #:  870108	0637 ]04	Approval Dat	12/29/1986	Verified:		
Docket Information DOCKET   NS 50364  WX	SS PLAN Farley 2, J. M.		uirements/Section SOURCE	SEC	CTION	 . <del>.</del>
Description Ratioanle	1-hour barrier; automa The licensee, by letter specifically for this fire miniflow, establish ma pressurizer PORVs, a intends to have these	g, electrical penetration tic fire suppression not dated March 13, 1985, area covering the man nual operation of the au nd initiate RCS chargin procedures fully implen stems associated with fi	installed. committed to develoual operator actions uxiliary feedwater sy g through the boron nented by the end of	op detailed procedur to regain charging p stem, regain control njection tank. The I the Unit 2 fourth ref	es oump of the icensee ueling outage.	 
Add Save	Delete: Clone-	GoTo	Search Screen	Correpondence Update	Keyword	
					`````	

•

.

.

emption #: [870	1080637 05 App	roval Dat 12/29/1986 Verified:	
cket Information	NSSS PLANT	Requirements/Section Information	
scription.	Unit 2 Auxiliary building vertical ca barrier. By letter dated March 13, 1985, the specifically for fire area 2-103 whic control of the pressurizer PORVs. All other safe shutdown systems a	le licensee committed to develop a detailed procedure ch will identify the manual operator actions required to regain the	
		Exity Correpondence Keyword	
Add	Delete Clone GoTo	Exit Search Screen Correpondence Vedate	
Add Sav	Ve Delete Cione Goto	Search Screen	

.

.

۳1

•

•,

	Exem	nption Record Input Screen
Exemption #: 1870108	0637 106	Approval Dat 12/29/1986 Verified:
Docket Information DOCKET   NSt 50364 WX	SS PLANT Farley 2, J. M.	Requirements/Section Information SOURCE Appendix R III.G.2.c.
Description	Unit 2 Auxiliary building, elect hour barrier, installation of aut	rical penetration (fire area 2-034), requires one train enclosed by 1-
Ratioanie	for this fire area covering man reactor coolant pump seal inje main steam atmospheric relie valves and initiating RCS char	larch 13, 1985, committed to develop detailed procedures specifically ual operator actions to regain charging pump mini-flow, establish ection, isolation of RCS and pressurizer sample lines, control of a f valve, regain control of pressurizer PORV and reactor head vent rging through the boron injection tank. The licensee intends to have nented by the end of the Unit 2 refueling outage.
Add Save	Delete	Exit Search Screen Correpondence Update Update
	· · · · · · · · · · · · · · · · · · ·	
	- 18 -	

.

## **Exemption Record Input Screen**

÷.

**Requirements/Section Information** 

Exemption #: 18701080637 807

Approval Dat 12/29/1986

Verified:

Docket Information

Add

50348

1

DOCKET NSSS PLANT SOURCE WX Farley 1, J. M. Appendix R 111.G.2 Description Unit 2 Auxiliary building, fire areas 2-009 and 2-076, require 1 train be enclosed in 1-hour rated barrier, installation of automatic fire detection in and 2-076. 2 mar 1 1 Ratioanie Therefore, by letter dated March 13, 1985, the licensee committed to protect one train of control cabling associated with the auxiliary feedwater isolation valves with a equivalent one-hour fire

barrier in fire areas 2-009, develop detailed procedures specifically for these fire areas with regard to regaining the control of a pressurizer PORV and isolating the Train B pressurizer PORV, reactor head vent and pressurizer block valves from a hot shot spurious signal. The licensee intends to have the raceway fire barrier installed and the procedures necessary to satisfy the fire effects

		te Clone	GoTo Exit	Search Screen	Correpondence Update	Keyword Update	
:	S. Barren and S.				······································	الوالف الأخلية مستخص معري الخار	

÷.

Exemption Record Input Screen	
Exemption #: 8701080637 108 Approval Dat 12/29/19861 Verified:	
Docket Information       PLANT         DOCKET       NSSS         50364       WX         Farley 2, J. M.         Description         Unit 2 Auxiliary Building, fire area 2-031 requires one train be enclosed in 1-hour rated fire barrier.	
Ratioanie The licensee, by letter dated March 13, 1985, committed to develop detailed procedures specifically for fire area 2-031 which identify the manual operator actions required to regain control of one main stream atmospheric relief valve and those actions necessary to monitor boron concentration utilizing the RCS sampling system. The licensee intends to have these procedures fully implemented by the end of the Unit 2 fourth refueling outage. All other shutdown systems associated with fire area 2-031 have redundant counterparts in other	
Add Save Delete Clone GoTo Exit Search Screen Correpondence Keyword Update	

. . ۰, \*• 2 • τ.

.

Exemption #:	dooccos		<b>Cemption</b>		nput Sc	reen	
		0105 13		00/23/1990	venned.		
OCKET	1 41 Carlos Carlos	SS (	Alexandra and a state of the second state of t	quirements/Sec	tion Informatio		3.745
50219	GE	Oyster Creek			II.G.2	SECTION	1273).
		•				;	
			in the second			•	
Description			······································		· · · · · · · · · · · · · · · · · · ·		· · · ·
		480V Switchgear Room shutdown free of fire da	i does not provide at image without repair.	least one safe sh	nutdown path to i	naintain hot	
							₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩
			·· <b>、</b>	•.			
Ratioanle		Identified operator action the cable bus tie, (2) cat (3) do not involve any tr components or tools. F the identified operator a assurance that hot shut	In be completed well ransit through the fire for the above reason actions including the	before any unrec affected zones, s we have detern minor repair in a	coverable reactor and (4) do not re nined that with th timely manner, tl	conditions occurs, quire any offsite e completion of all here is reasonable	
Add	Save	Delete	GoTo	Search Scre	Correponden	dence te	
						الغانين الالتلاط المتعين من عن المعاد المعروبي. 	
							-
						2	
	and the second						

. . .

•