

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Steve R. Harter
dba Green Country Wireline
P.O. Box 13
Dewey, Oklahoma 74029

2. NRC/REGIONAL OFFICE

USNRC Region IV
611 Ryan Plaza Drive
Arlington, Texas 76011-4005

REPORT NUMBER(S) 2004-001

3. DOCKET NUMBER(S)

030-20307

4. LICENSEE NUMBER(S)

35-23145-01

5. DATE(S) OF INSPECTION

11/29/2004

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Rick Muñoz	/RA/	11/29/04

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Steve R. Harter dba Green Country Wireline REPORT NUMBER(S) 2004-001		2. NRC/REGIONAL OFFICE USNRC Region IV	
3. DOCKET NUMBER(S) 030-20307	4. LICENSE NUMBER(S) 435-23145-01	5. DATE(S) OF INSPECTION November 29, 2004	
6. INSPECTION PROCEDURES USED 87123	7. INSPECTION FOCUS AREAS 03.01 through 03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 03111	2. PRIORITY 03	3. LICENSEE CONTACT Steve R. Harter, RSO	4. TELEPHONE NUMBER 817-534-2107
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: November, 29 2007	
<input type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

This is a small wireline operation with four employees including the RSO. The licensee uses a single 3 Curie Am-241 beryllium source. Green Country Wireline (GCW) conducts wireline operations from temporary job sites in both NRC and agreement states. GCW holds a State of Oklahoma license expired August 2003 but was deemed timely. They conducted logging operations approximately 10-20 times monthly. Since the last inspection, all work noted was conducted in Oklahoma and Kansas. No work had been performed in NRC jurisdiction for the inspection period. It appeared that the down hole storage vault had not been used. Access to the area was impossible due to hay bales covering the storage entrance. The RSO indicated that the source was used often enough to store and lock the source in the wireline truck vault.