

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Pacific Testing Services, Inc REPORT NUMBER(S) 04-01		2. NRC/REGIONAL OFFICE USNRC Region IV	
3. DOCKET NUMBER(S) 030-34643	4. LICENSE NUMBER(S) 53-29118-01	5. DATE(S) OF INSPECTION November 18, 2004	
6. INSPECTION PROCEDURES USED IP87121		7. INSPECTION FOCUS AREAS 03.01-03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3310	2. PRIORITY 1	3. LICENSEE CONTACT Richard Leipertz	4. TELEPHONE NUMBER 808-487-3503
-----------------------------------	-------------------------	--	--

Main Office Inspection
 Field Office
 Temporary Job Site

Next Inspection Date: _____

PROGRAM SCOPE

Small industrial radiography company. Richard Leipertz is President. Gary Wood is General Manager, Richard Leipertz is RSO, Ryan Carny is Assistant RSO. License authorizes industrial radiography and portable gauge use. Licensee has one camera and 3 portable gauges. (Troxler 3400 series). Usage is daily, mainly on military bases and refineries. Security was adequate. Instrumentation was calibrated at the proper frequency and current. All radiation safety documentation was in order. Licensee staff is very radiation safety conscious. Highest whole body TEDE: 157 mrem in 2003; 236 mrem in 2004 (at the time of inspection).

Last inspection was July 2002. There was one Severity Level IV violations involving failure to conduct an annual radiation safety program review. Licensee had implemented a program review and conducted reviews in August 2004 and February 2004. This violation is closed.

This inspection revealed one Severity Level IV violation involving failure to conduct a public dose assessment in accordance with 10 CFR 20.1301.

License was instructed how to accomplish assessment using guidance in NUREG 1556, Volume 2, and indicated that the review would be done within 30 days, as was documented on the NRC Form 591M, Part 1 and issued onsite.