		Region I - DNM	IS Licensee Eve	ent Report		
	Licensee:	GREEN BAY PACKAGING	GINC			
Event Description:		Stuck Shutter on Ohmart OD-120 Base Gauge Medel BAL				
		Source Houst	719		,	
License No:	4	5-25268- Docket No:	0303327	MLER-RI:	2004 -	065
Event Date:	$\overline{\it u}$	-11-04 Report Date:	11-11-04	HQ Ops Event #:	4119	0
1. RE	PORTING F	REQUIREMENT				
	10 CF	R 20.1906 Package Contaminat	ion X	10 CFR 30.50 Rep	ort	ta (t. f. t.)) Haff (the hair)
 		R 20.2201 Theft or Loss		10 CFR 35.3045 M		
		R 20.2203 30 Day Report		License Condition		
—	Other	•	Alliedad of sääddet et	Criceiise Coliginati		i.diialii-tt lii
) DE	EGION I RES	Parameter Company				
1 2. RE						diel additi
		diate Site Inspection			Johanne	12/2/04
		al Inspection	ARRIGHAN DE LE L	pector/Date		
	Teleph	none Inquiry	Insp	pector/Date		47.5
	Prelim	inary Notification/Report		Daily Report		
2	Inform	ation Entered in RI Log		Review at Next I	nspection	i i de la
	Report	t Referred To:	NHED 040	807		
3. RI	EPORT EVA	ALUATION				
>	Descri	ption of Event	Corrective Ac	ctions		
	Levels	of RAM Involved	Calculations	Adequate		
	Cause	of Event	Additional Inf	formation Requested	from Licensee	
4. M/	ANAGEMEN	NT DIRECTIVE 8.3 EVALUATION	Hindred Lee 11 of 11 of			
	Releas	se w/Exposure > Limits	Deliberate M	//isuse w/Exposure >	Limits	
		ited Inadequate Control		ure>10 rads/hr or Cor		lv I imite
		ure 5x Limits		s w/Exp>Limits or M		1 1 1 1 2 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1
	111 1111	ial Fatality		umstances or Safegu	医抗性神经病 医静脉管 化	de Enecis
	1.14	of the above are involved:		unstances of Saleyt		
	- 1	dered Need for IIT	Considered	Need for AIT		
		on/Made By/Date:	N/A OL	Acces 12/	didahalik kilibidid 14154	A Parent Land Land Constitute (
5. N		NT DIRECTIVE 8.10 EVALUATI	ON (additional pyolus	tion for modical over	uto oply)	
J		(数) 2 () () () () () () () () ()	kandidan berberak			
_		liness - Inspection Meets Requir	Minda Makilo Translavo.		s for underexposu	ure) ,[[[[[[[
_	14.45,45	cal Consultant Used-Name of Co			578. 1 . 1 +4555 15	. Its tale est
		cal Consultant Determined Even	MIRRINGER CONTRACTOR	to Fatality		
	Device	ce Failure with Possible Adverse	Generic Implications			
L.	но о	or Contractor Support Required to	o Evaluate Consequer	nces		
6. SF	ECIAL INS	TRUCTIONS OR COMMENTS	Francisco (Control of Control of			
	TSPZ PE	In 12/2/04 No	experses to	personul.	shatter fix	ad
L 9	perge 1	eturnal to open	ton.	•		
Public:		Signature:	Jane for	Ramor_		
Non-Public:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Date:	/12/14/04			
Location of File	: G:\Refere	ence\Blank Forms\2004 LER FO	RM.wpd /		R	Rev. 11/18/04



45-25268-4

Green Bay Packaging Inc.

Winchester Coated Products Division

November 23, 2004

United States Regulatory Commission Region I 475 Allendale Road King Of Prussia, Pennsylvania 19406-1415

To Whom It May Concern:

This letter is a follow up to the phone report made to Bill Huffman on November 11, 2004, event # 41190. At 6:30 on November 11, 2004 we experienced a stuck shutter on our Ohmart OD-120 base gauge. All necessary preventions were taken to limit exposure, and a call was made to Honeywell/Measurex for a service man to repair. All repairs were completed by 2:50 PM on November 11, 2004 and gauge returned to service with no further problems.

Thank You,

Michael Dickey, RSO

Winchester Coated Products

Mulacl Dickey

Green Bay Packaging Inc.

cc: Tom Schibly

20: 24 62 VON 40

RECEIVED

SPECIALISTS IN COATED SELF-ADHESIVE MATERIALS