

Engineering Branch 1 Finding 10/01/2003-12/31/2003

Site/Number	Type	Title
Catawba 2003004-02	NCV	Effect of RCP Thermal Barrier Rupture on MOV Closure and Containment Isolation
Browns Ferry 2003007-01	URI	Inadequate Unit 3 Fire Procedure Directs Local Manual Operator Action Be Performed In Location of Fire
Browns Ferry 2003007-02	NCV	Changes Made to the Fire Protection Program Regarding Compensatory Fire Watch Implementation Without NRC Approval
St. Lucie 2003013-01	NCV	Failure to Evaluate Combustible Loading of Silicone Oil-Filled Transformers in the FHA and the Effect on SSD Capability
Surry 2003004-01	NCV	Emergency Diesel Generator No. 3 Bus-Tie Breaker Control Circuit Design Deficiency
Crystal River 2003005-02	NCV	Failure to Protect One Train of Safe Shutdown Equipment From Fire Damage
Brunswick 2003008-01	URI	Failure to Adequately Consider Vortexing in the Calculation for CST Level for Automatic Transfer of the HPCI Pump Suction
Harris 03-07-01	NCV	Inadequate Implementation of the FPP for SSD
Harris 03-07-02	NCV	Inadequate Corrective Action for a Previous White Fire Protection Finding

July 19, 2004 (1:04PM)

P:\findings_eb1_opplan_data.wpd

KK-3

17

2