NRC FORM 591M PART 1 (10-2003)		U.S. NUCLEAR REGULATOR	RY COMMISSION
10 CFR 2.201	NSPECTION REPORT A	ND COMPLIANCE INSPECTION	
1. LICENSEE/LOCATION INSPECTED: City of Twin Falls 321 2 nd Avenue East Twin Falls, Idaho REPORT NUMBER(S) 2005-001		2. NRC/REGIONAL OFFICE USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005	
3. DOCKET NUMBER(S) 030-32235	4. LICENSEE NUMBER(S) 11-27081-01	5. DATE(S) OF INSPECTION February 16, 2005	
LICENSEE:	11-27001-01	February 16, 2005	
The inspection was an examination of th Nuclear Regulatory Commission (NRC) of procedures and representative records X	rules and regulations and the conditions s, interviews with personnel, and observatings, no violations were identified. described to you by the inspector as nonction was or is being taken, and the remated. ation(s) was/were discussed involving the discussion of your activities, as described below a DF VIOLATION, which may be subject to	e as they relate to radiation safety and to compliance with of your license. The inspection consisted of selective exations by the inspector. The inspection findings are as for cited violations, are not being cited because they were seining criteria in the NRC Enforcement Policy, NUREG-16 following requirement(s) and Corrective Action(s): and/or attached, were in violation of NRC requirements are posting in accordance with 10 CFR 19.11.	xaminations collows: elf-identified, 00, to
	censee's Statement of Correcti		
corrective actions is made in accordance	with the requirements of 10 CFR 2.201	Il be taken to correct the violations identified. This statem (corrective steps already taken, corrective steps which will sponse to NRC will be required, unless specifically reque Signature	ll be taken,
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR James L.	Thompson	/RA/	2/16/2005