

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED: Haley and Aldrich, Inc. 465 Medford Street, Suite 2200 Cambridge, MA 02129-1400</p> <p>REPORT Nos 2005-001</p>	<p>2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415</p>
---	---

<p>3. DOCKET NUMBER(S) 030-34373</p>	<p>4. LICENSE NUMBER(S) 20-20825-02</p>	<p>5. DATE(S) OF INSPECTION 4-20-2005</p>
--	---	---

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

License Condition 14.A. requires the gauge to be tested for leakage and/or contamination every 6 months. Contrary to the above, between 11/7/03 + 1/6/05, Humboldt Model 5001 (s/n 3692) was not leak tested every 6 months. No leak tests were done in 2004. The licensee has a new RSO - in training at corporate and a local RSD at the McLean, VA office. The local RSD performed a leak test in 2005 and will →

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	David A. Schenckhoff	<i>David A. Schenckhoff</i>	4-20-05
NRC INSPECTOR	Kathy Dolce Modes	<i>Kathy N. Modes</i>	4-20-05

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Haley and Aldrich, Inc. 465 Medford Street, Suite 2200 Cambridge, MA 02129-1400 REPORT NUMBER(S) 2005-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
3. DOCKET NUMBER(S) 030-34373	4. LICENSE NUMBER(S) 20-20825-02	5. DATE(S) OF INSPECTION 4-20-05	

(Continued)

Continue to leak test the gauges in their possession every 6 months. Records will be maintained at the McLean, VA. office. Licensee will leak test gauges on a January/July schedule.

10 CFR 20.1101(c) requires the licensee to audit their radiation safety program annually. Contrary to the above, the licensee did not audit their program in 2004. The local RSO performed an audit in February 2005 and will continue to audit the McLean, VA office every year.