

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Twin Ports Testing
1301 N 3rd St
Superior, WI
REPORT 2005001

2. NRC/REGIONAL OFFICE

US NRC Reg 111
2443 Warrville Rd
Suite 210
Lisle, IL 60532

3. DOCKET NUMBER(S)

03022241

4. LICENSEE NUMBER(S)

48-23476-01

5. DATE(S) OF INSPECTION

Aug 16, 2005

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	G. Parker		8/16/05

**Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Twin Ports Testing REPORT NUMBER(S) 2005-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-22241	4. LICENSE NUMBER(S) 48-23476-01	5. DATE(S) OF INSPECTION August 15, 2005	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01 - 03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT David Rands	4. TELEPHONE NUMBER 715/382-7114
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: 8/06	
<input type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

The licensee is a radiographer located in Superior, Wisconsin with authorization to use material at temporary job sites where the NRC has jurisdiction. This licensee has three full time radiographers and owns six 660B exposure devices.

Performance Observations

At the time of the inspection, licensee was not performing radiography within a two hundred mile radius of the corporate office. Therefore no temporary job site was observed. The inspector reviewed the paperwork associated with the transfer of the radiographic devices interviewed personnel that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.

Independent surveys around the storage facility yielded minimal results. Although licensee personnel are badged, readings for the past year were low and did not exceed 750 mrem on average.

No violations of requirements were noted.