


From: [Redacted] *70*
 To: <etb@nrc.gov>
 Date: Sun, Oct 22, 2000 9:47 AM
 Subject: Allegations Question

Below is the result of your feedback form. It was submitted by [Redacted] on Sunday, October 22, 2000 at 09:47:01



Comments: Has the control room pressurization problem ever been fixed at Salem 1/2? To the best of my recollection back in 1996 and 1997 they had a couple of people propping open doors to obtain .125in w/g required air pressure in the control room. This remedy is or was used during the emergency and maintenance modes. *10*



Submit2: Submit

Information in this record was deleted in accordance with the Freedom of Information Act, exemptions *7C*
 FOIA- 2004-314

N-20