

M. Patel
J. Hernandez

From: MPP1, JEH3, VMR1 (Veronica Rodriguez) *RT*
To: DRP; DRS; ORA; PM
Date: Tue, Apr 27, 2004 3:09 PM
Subject: DRPnews

Special Inspection at Vermont Yankee - Missing Spent Fuel Segments

Records indicate that the two fuel pin segments ~~were inserted into the pipes~~ for storage in 1980 following a failed fuel disassembly and reconstitution effort. Instead of performing a "piece count" of the fuel pin segments in the bucket, Entergy personnel ensured the bucket remained upright and in place at the bottom of SFP.

For more information: <http://r1ntweb.nrc.gov/drp/Drp.htm>

CC: Hernandez, Jorge; Manan Patel

C-97