

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE Wallace & Associates REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-36875	4. LICENSE NUMBER(S) 21-32557-01	5. DATE(S) OF INSPECTION January 31, 2006	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT David A. Chenoweth, RSO	4. TELEPHONE NUMBER 269-273-3205
------------------------------------	-------------------------	---	--

Main Office Inspection Next Inspection Date: **January 2011**

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE

The licensee was a roofing company, a subsidiary of Chenoweth Roofing, that performed moisture testing of roofs and roofing materials in southern Michigan. The licensee possessed one Troxler 3216 gauge for occasional use. The licensee had used the gauge three times since June 2005. The gauge was properly secured in storage at the location specified in the license. The licensee did not perform any service or maintenance activities on the gauge. The licensee had employed three gauge users who had completed the manufacturer's gauge training course.

Performance Observations

No temporary job site was available at the time of the inspection. The radiation safety officer (RSO) described transportation, security, and emergency procedures for the gauge, and demonstrated the use of the gauge. In addition, the RSO described procedures for leak testing and inventorying the gauges. Interviews with licensee personnel indicated sufficient knowledge of radiation safety procedures and policies.