

<b><u>Alleger-Supplied TARP Reports That May Need Follow-Up</u></b>	
<b>Brief Description</b>	<b>Follow-Up Action/Assessment</b>
<b>Evaluate decision to perform a complete station air outage while online</b> (eventual impact was a 75gpm reactor coolant leak from the Pressurized Relief Tank). [20133239] (NON-CONSERVATIVE DECISION MAKING)	
<b>Evaluate Corrective Action Program</b> for response to severe grassing event. Two <b>severe Grassing Events 26 days apart</b> in March of 2003. [20124025 & 20137707] (CORRECTIVE ACTION PROGRAM EFFECTIVENESS)	
<b>Evaluate Corrective Action Program &amp; Operability Review Quality</b> for resolution of multiple failures and repeated entries and exits of T.S. Action Statements of <b>Containment Fan Cooler Units (CFCU)</b> in December of 2002. [20125714 & 20125678] (CORRECTIVE ACTION PROGRAM EFFECTIVENESS)	
<b>Evaluate Corrective Action Program</b> for resolution of <b>Circulating Water System problems</b> (high silt levels causing excessive wear on screens, complacent maintenance on non-safety related components, grassing, etc.) in March of 2002. (CORRECTIVE ACTION PROGRAM EFFECTIVENESS)	
<b>Investigate temporary modification</b> to provide temporary power to the Met Tower building to <b>avoid issuing a 50.72 report</b> . [20095181] (CONFIGURATION CONTROL OF T.S. EQUIPMENT)	

<b><u>Winston &amp; Strawn Interviews Reviewed by Rick Urban</u></b>	
<b>Brief Description</b>	<b>Follow-Up Action/Assessment</b>
<b>Assess impact of the Hope Creek EDG fuel linkage binding</b> described in the Kurt Kreuger interview (pages #?# - #?#). (OPERABILITY DETERMINATION QUALITY)	Reviewed in routine Resident Inspector (RI) inspection report 50-354/2003-003, section 40A4 & 40A7. No additional follow-up needed.

G:\DRP\BRANCH3\Allegation SCWE\Salem-HC-InterviewIssuesReview.wpd

B-211

### **NRB Issues That May Need Follow-Up**

<b>Identifier</b>	<b>Brief Description</b>	<b>Follow-Up Action/Assessment</b>
Mtg minutes No. 00-02		

G:\DRP\BRANCH3\Allegation SCWE\Salem-HC-NRB-Review.wpd