NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION							
(10-2003) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
SAFEI	TINSPECTION	REPURI AND C	OWPLIANCE INS	PECTION			
1. LICENSEE/LOCATION			2. NRC/REGIONAL OFFICE	L. Campa			
Hibbing Taconite Corp			2. NACHEGIONAL OFFICE, US Nuclear Regulatory Comm 2443 Warmanville Kd Suite 210 Lisk, II 60632				
7.0. Box 589			Suite 210				
Hibbing, MN 55746			Lisk. I) 60532				
REPORT 200600 I		·					
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		5. DATE(S) OF IN	SPECTION		
03011327		22-14735-01		Feb 23, 2006			
LICENSEE:							
Nuclear Regulatory Cor of procedures and repre	nmission (NRC) rules and esentative records, intervi	I regulations and the cond ews with personnel, and o	itions of your license. The	diation safety and to compliant inspection consisted of sele or. The inspection findings a	ctive examinations		
1. Based on the inspection findings, no violations were identified. 2. Previous violation(s) closed.							
 The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied. 							
Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):							
* • • • • • • • • • • • • • • • • • • •							
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.							
(Violations and Corrective Actions)							
•	•				!		
					,		
Licensee's Statement of Corrective Actions for Item 4, above.							
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken,							
date when full compliance	e will be achieved). I unde	rstand that no further writte	n response to NRC will be	required, unless specifically re	equested.		
Title	Printe	ed Name		gnature	Date		
LICENSEE'S REPRESENTATIVE	· · · · · · · · · · · · · · · · · · ·			 			
NRC INSPECTOR	6. Parker		JE AL		a/23/06		

Issue Date: 11/25/03

E8-1 (

2800, Enclosure 8

Docket File Information SAFETY INSPECTION REPOR AND COMPLIANCE INSPECTION	
2. NRC/REGIONAL OF	FFICE
Region III	
4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
22-14735-01	February 23, 2006
7. INSPECTION FOCUS AREAS	
2800/035 01 through 10.4	
SUPPLEMENTAL INSPECTION INFORMA	ATION
3. LICENSEE CONTACT	4. TELEPHONE NUMBER
Larry Lokken	218/262-6811
Next Inspecti	ion Date:
Mining operations Hibbing, Mn	
	SAFETY INSPECTION REPORAND COMPLIANCE INSPECTION 2. NRC/REGIONAL O Region III 4. LICENSE NUMBER(S) 22-14735-01 7. INSPECTION FOCUS AREAS 2800/035 01 through 10.4 SUPPLEMENTAL INSPECTION INFORMA 3. LICENSEE CONTACT Larry Lokken Next Inspect

PROGRAM SCOPE

The scope of this inspection was limited to the procedures described in Temporary Instruction 2800-035. This licensee is a taconite mine located in the Mesaba Range near Hibbing, Minnesota. The licensee is authorized under its license to possess and use the subject material for process control of mining operations. The NRC inspector reviewed documentation and determined that the subject material is owned by the licensee.

Performance Observations

The inspector toured the licensee facilities and conducted a physical inventory of the subject material. The subject material was accounted for and no discrepancies in the inventory were observed. The material was physically verified during the inspection. The inspector considered security of the material to be adequate. Upon examination of licensee's paperwork, subject material was determined to be owned by the licensee as stated in its Form 742 report.

No violations of NRC requirements were identified.