LR-N06-0097



MAR 0 1 2006

United States Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

SPECIAL REPORT HOPE CREEK GENERATING STATION FACILITY OPERATING LICENSE NPF-57 DOCKET NO. 50-354

This special report is being submitted pursuant to the requirements of Hope Creek Technical Specification (TS) 3.3.7.5, "Accident Monitoring Instrumentation" Action 81, due to the Filtration Recirculation Ventilation System (FRVS) radiation monitor being inoperable for greater than 72 hours.

On February 15, 2006 at 0800, TS 3.3.7.5 was entered due to the FRVS radiation monitor being inoperable for a scheduled calibration of the flow monitor. During the performance of the calibration of the flow monitor, the high flow power supply was determined to be degraded on February 16, 2006. Repairs to the high flow power supply were completed on February 17, 2006, with the replacement of the power supply printed circuit board. Calibration of the flow monitor was resumed and on February 18, 2006, the low flow power supply was also determined to be degraded. Troubleshooting was performed that determined that capacitors C2 and C8 and voltage regulator VR2 needed to be replaced. The low flow power supply was repaired on February 19, 2006, and the calibration of the flow monitor was completed satisfactorily. The FRVS radiation monitor was returned to an operable status on February 19, 2006, at 2211 hours.

Should there be any questions regarding this matter please contact Michael Jesse at 856-339-1280.

Sincerely,

Michael J. Massaro Plant Manager – Hope Creek

192

95-2168 REV. 7/99

Document Control Desk LR-N06-0097

C Mr. S. Collins, Administrator- Region I United States Nuclear Regulatory Commission 474 Allendale Road King of Prussia, PA 19406

USNRC Senior Resident Inspector – Hope Creek (x24)

Distribution