



July 14, 2006

L-2006-182
10 CFR 50.4


U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: St. Lucie Unit 1
Docket No. 50-335
NRC Bulletin 2004-01 Update
Pressurizer Replacement

In the responses to NRC Bulletin 2004-01 via letters L-2004-160 and L-2005-011 dated July 27, 2004 and January 18, 2005, respectively, FPL stated that the St. Lucie Unit 1 pressurizer was scheduled for replacement during the SL1-20 refueling outage. FPL completed the pressurizer replacement during the SL1-20 refueling outage via Plant Change Modification (PCM) 04149. The NRC docketed its inspection of the pressurizer replacement and associated activities in the NRC Integrated Inspection Report 05000335/2005005 and 05000389/2005005.

Please contact Ken Frehafer at (772) 467-7748 if there are any questions on this matter.

Very truly yours,


Gordon L. Johnston
Vice President
St. Lucie Plant

GLJ/KWF

A110