

**U.S. NUCLEAR REGULATORY COMMISSION**

Date: 9/22/2006

**TELEPHONE CONVERSATION RECORD**

Time: 1040

Mail Control 2006001 License No(s). 42-32219-01 Docket No(s). 03035252  
or Report No(s).

Name of Licensee: Team Industrial Services (TIS)

Name of Participant(s): Don Hinman TIS Operations Manager  
Jim Schmidt, RI Health Physicist

Telephone No. 800-220-1517

Subject: Team Inspection Information Regarding Defective Control Assembly Use  
(NOTE: This will be used as the Documents Title in ADAMS)

Summary: I spoke to Don Hinman (Team Industrial Operations Manager) and attempted to determine how often the control assembly had been used prior to the misconnect event. Here is the information Mr. Hinman provided:

1) After the event, all four of the control assemblies purchased by the licensee were found to allow attachment of the assembly to the camera even though the pigtail was not connected to the control cable (as stated in my report).

2) To the best of his knowledge (since detailed records are not kept of which control assembly is used when), one of the assemblies was never used, two were used about a dozen times each, and the one involved with the misconnect event was used about four times prior to the misconnect event.

Action Required: Enter this document into ADAMS

Document Availability:  Publicly Available  Non-Publicly Available

Non-Sensitive  Non-Sensitive Copyright  Sensitive  Sensitive Copyright

Immediate Release  Normal Release  Delay Release Date

Prepared &amp; SUNSI Review Completed By: Jim Schmidt / RA / Date: 9/22/06