

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

September 26, 2006

Attn: Lloyd Gray Radiation Safety Officer Acuren Inspection, Inc. 101 Underwood Road, Bldg. J La Porte, Texas 77571

SUBJECT: NRC INSPECTION REPORT 030-34780/2006-002 (FORM 591M Part 1)

Dear Mr. Gray:

This letter and the enclosed NRC Form 591M refer to the inspection conducted on June 28 and July 14, 2006, at your facility located in St. Croix, U.S. Virgin Islands. A preliminary exit briefing was conducted with Mr. David Oetken, Compliance Manager at the conclusion of the onsite inspection. Final exit briefings to discuss the inspection findings were conducted telephonically with you and with Mr. Ken Stankievech, President, on August 24, 2006.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, independent measurements, and observation of activities in progress.

Within the scope of this inspection no violations or deviations were identified; therefore, no response to this letter or the enclosed NRC Form 591M is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html.

Should you have any questions concerning this inspection or the enclosed report, please contact the undersigned at (817) 860-8143.

Sincerely,

/RA/

Randy R. Erickson Nuclear Materials Inspection Branch

Docket No.: 030-34780 License No.: 42-27593-01

Enclosure: As stated

cc w/enclosure:

Texas Radiation Control Program Director

Acuren Inspection, Inc.	-2-
bcc w/enclosure (via ADAMS e-mail distribut LDWert CLCain VHCampbell JEWhitten RITS Coordinator NMIB RIV Materials Docket Files - 5th Floor	rition):
SUNSI Review Completed: RRE	
ADAMS: <u>⊠</u> Yes <u>□</u> No Initials: <u>F</u>	<u>RRE</u>
□ Publicly Available □ Non-Publicly Availa	ble □Sensitive ⊠Non-Sensitive
DOCUMENT NAME: s:\dnms\!nmib\!ericksc	on\63478002-591M.wpd final r:_dnms
RIV:DNMS:NMIB	
RRErickson /RA/	
09/07/06	
OFFICIAL RECORD COPY	T=Telephone E=E-mail F=Fax

(10-2003)	NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION (10-2003)					
10 CFR 2.201	SAFETY INSPI	ECTION REPORT AN	D COMPLIANC	E INSPECTION		
LICENSEE/LOCATION INSPECTED: Acuren Inspection, Inc. 101 Underwood Road, Bldg. J La Porte, Texas 77571		2. NRC/REGIONAL OFFICE US NRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005				
REPORT	2006-002					
3. DOCKET NUMBER(S) 030-34780		4. LICENSEE NUMBER(S) 42-27593-01		5. DATE(S) OF INSE June 28, 2006 and July		
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X						
cited. This form		activities, as described below and TON, which may be subject to po		violation of NRC requirements ar vith 10 CFR 19.11.	nd are being	
corrective actions is made	30 days, the actions desc e in accordance with the re will be achieved). I under	equirements of 10 CFR 2.201 (c	be taken to correct the orrective steps already	n 4, above. e violations identified. This stater v taken, corrective steps which w required, unless specifically requi Signature	ill be taken,	
NRC INSPECTOR	Randy R. Erickson	 on		/RA/	09/07/2006	