

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Acceliner Service Company, Ltd. d/b/a Oncology Services International. 500 N. Franklin Turnpike, MB8, Ramsey, NJ 07446		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT Nos 2006-026			
3. DOCKET NUMBER(S) 99990001	4. LICENSE NUMBER(S) File No. 184	5. DATE(S) OF INSPECTION March 15, 2006 - August 11, 2006	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

10 CFR 40.25(d)(4) requires a general licensee who receives, possesses, or uses depleted uranium pursuant to a general license to report in writing, within 30 days of any transfer, to the Director, Division of Industrial and Medical Nuclear Safety, with a copy to the Regional Administrator of the appropriate Regional Office, the name and address of the person receiving the source material pursuant to such transfer.

Contrary to the above, the licensee did not provide written notification to NRC within 30 days of transfer of DU the name and address of the person receiving source material. Specifically, from February 2004 - March 2006, Acceliner Services, International, d/b/a Oncology Services International received 12 linear accelerators containing DU and made 4 separate shipments of DU and did not provide written notification to NRC of the transfers. Upon identification, the licensee provided records of receipt and transfer to NRC, and submitted an application to NRC for a specific license. This licensee identified and corrected violation was dispositioned as a SL IV, Supplement IV Non-cited Violation (NCV) .

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Randolph C. Ragland, Jr.	<i>Randolph C. Ragland Jr.</i>	8/11/2006

SUNSI Review Completed By: / RA / Randolph C. Ragland, Jr. Public Non-Sensitive