

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Mid American Inspection REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-31160	4. LICENSE NUMBER(S) 21-26060-01	5. DATE(S) OF INSPECTION October 3, 2006	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT Terry Wilkins	4. TELEPHONE NUMBER 989/732-8059
-----------------------------	------------------	--------------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: 10/07
 Field Office _____
 Temporary Job Site _____

PROGRAM SCOPE

The licensee is a radiographer located in Gaylord, Michigan with authorization to use material at temporary job sites. This licensee has four full time radiographers and owns six 660B exposure devices.

Performance Observations

At the time of the inspection, licensee was performing radiography along Michigan route 30. Therefore this temporary job site was observed. The inspector found that the radiography crew had all the proper paper work with them and that when interviewed, had a good understanding of radiation safety. During the period of observation, the crew followed all safety requirements.

The inspector reviewed the paperwork associated with the use of the radiographic devices at the main office and interviewed personnel there that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.

Independent surveys around the storage facility yielded minimal results. Although licensee personnel are badged, readings for the past year were low and did not exceed 1000 mrem on average..

No violations of requirements were noted.

