

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: Hubbell, Roth & Clark 2001 Centerpoint Pkwy, Suite 109 Pontiac, MI  REPORT NUMBER(S) 2006/001		2. NRC/REGIONAL OFFICE  REGION III US NUCLEAR REGULATORY COMMISSION 801 WARRENVILLE ROAD LISLE IL 60532-4351	
3. DOCKET NUMBER(S) 030-33835	4. LICENSE NUMBER(S) 21-26646-01	5. DATE(S) OF INSPECTION 11/30/2006	

**LICENSEE:**  
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

\_\_\_\_\_ non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE			
NRC INSPECTOR	Sarah Bakhsh	<i>Sarah R Bakhsh</i>	11/30/2006

**Docket File Information**  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: Hubbell, Roth & Clark REPORT NUMBER(S) 2006/001		2. NRC/REGIONAL OFFICE REGION III	
3. DOCKET NUMBER(S) 030-33835		4. LICENSE NUMBER(S) 21-26646-01	5. DATE(S) OF INSPECTION 11/30/2006
6. INSPECTION PROCEDURES USED IP 87124		7. INSPECTION FOCUS AREAS 03.01-03.07	

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Marshall Grazioli, RSO	4. TELEPHONE NUMBER 248-388-9241
-----------------------------	------------------	---	-------------------------------------

Main Office Inspection                      Next Inspection Date: 11/2011

Field Office Inspection \_\_\_\_\_

Temporary Job Site Inspection Southfield, Michigan

**PROGRAM SCOPE**

The licensee was an engineering company located in Pontiac, Michigan. The licensee possessed an NRC license, authorizing it to conduct licensed activities using moisture/density gauges. The company owns 13 moisture/density gauges and employees 15 authorized users. The licensee conducts licensed activities using these gauges at temporary job sites in and around Detroit, Michigan.

Two gauges were in use at temporary job sites during the inspection. A temporary job site in Southfield, Michigan was inspected during the 11/29/2006 inspection.

**PERFORMANCE OBSERVATIONS**

During the inspection, the inspector observed: (1) adequate security of the licensed material; (2) adequate posting of areas; (3) demonstrations of emergency response procedures; (4) security during transportation; (5) demonstrations of gauge usage at temporary job sites; and (6) event response. The inspector reviewed records which included authorized user training certificates, leak tests, shipping papers, inventories, and utilization logs.

No violations of NRC requirements were identified.