

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE U. S. Inspection Services REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-35059	4. LICENSE NUMBER(S) 34-06943-02	5. DATE(S) OF INSPECTION November 27, 2006	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT Chris Dixon	4. TELEPHONE NUMBER 937/228-9729
-----------------------------	------------------	------------------------------------	-------------------------------------

Main Office Inspection
 Field Office
 Temporary Job Site

Next Inspection Date: 12/07 11/07

PROGRAM SCOPE

The licensee is a radiographer located in Dayton, Ohio with authorization to use material at temporary job sites where the NRC maintains jurisdiction. This licensee has twelve full time radiographers and radiographer assistants and is in possession of ten 660B and 880 exposure devices.

Performance Observations

Licensee is located in an Agreement state and as such the inspection was of limited scope. No temporary job site was observed as the closest was three hours away. The inspector reviewed the paperwork associated with the use of the radiographic devices and interviewed personnel that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.

Independent surveys around the storage facility yielded minimal results. Although licensee personnel are badged, readings for the past year were low and did not exceed 1000 mRem/yr on average.

No violations of requirements were noted.