



**Appendix B**  
**Photos of Sr-90 Source**



**Photo A - Photo of Source Assembly with collimator separated from source cylinder**



This photo is an end-on view of the source cylinder, showing the damaged foil

**Photo B - Damaged Foil**