

From: "Hinrichs, Gary H" <ghinric@entergy.com>
To: "James Noggle" <JDN@nrc.gov>, "Timothy Rice" <tbrace@gw.dec.state.ny.us>
Date: Mon, Nov 20, 2006 4:24 PM
Subject: Unit 2 SFP fuel transfer canal pictures

Here are the photos we attached to the CR we wrote for the transfer canal indications:

CC: "John White" <JRW1@nrc.gov>, "Croulet, Donald K" <dcroule@entergy.com>

B/24



Figure 1
SFP's Transfer Canal (Top View)




Figure 2
SFP's Transfer Canal (Location shown by arrow)



Figure 3
East Wall and South Wall - Outside Corner
Seam Weld



Figure 4
East Wall and South Wall - Outside Corner
Seam Weld



Figure 5
North Wall - Plug Weld



Figure 6
North Wall - Plug Weld




Figure 7
East Wall and North Wall - Inside Corner
Seam Weld




Figure 8
West Wall - Sleeve Penetration for Transfer
Tube
(Apparent Corrosion About Pen Weld)