

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

March 2, 2007

Randall K. Edington Senior Vice President, Nuclear Mail Station 7602 Arizona Public Service Company P.O. Box 52034 Phoenix, AZ 85072-2034

SUBJECT: ANNUAL ASSESSMENT LETTER - PALO VERDE NUCLEAR GENERATING

STATION (NRC INSPECTION REPORT 05000528/2007001, 05000529/2007001.

05000530/2007001)

Dear Mr. Edington:

On February 7, 2007, the NRC staff completed its performance review of the Palo Verde Nuclear Generating Station (PVNGS). Our technical staff reviewed performance indicators for the most recent quarter and inspection results for the period from January 1 through December 31, 2006. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility.

This performance review and enclosed inspection plan do not include physical protection information. A separate letter designated and marked as "Official Use Only - Security-Related Information" will include the physical protection review and resultant inspection plan.

Overall, PVNGS, Units 1 and 2, operated in a manner that preserved public health and safety and met all cornerstone objectives with a moderate degradation in safety performance. The performance of Units 1 and 2 for the most recent quarter was within the Degraded Cornerstone column of the NRC's Action matrix based on one Yellow finding, open since the fourth quarter of 2004, in the Mitigating Systems cornerstone. The finding involved a significant section of containment sump safety injection piping that was void of water at all three Palo Verde Nuclear Generating Station units.

Unit 3 was also operated in a manner that preserved public health and safety. While all cornerstone objectives were also met for Unit 3, we have assessed the performance of Unit 3 to be in the Multiple/Repetitive Degraded Cornerstone column of the NRC's Action Matrix effective the fourth quarter of 2006. On February 21, 2007, the NRC staff forwarded a letter concerning the final significance determination of a White inspection finding in the Mitigating Systems cornerstone (ADAMS Reference ML070530206). The inspection finding is associated with failures of the Unit 3, Train A emergency diesel generator on July 25 and September 22, 2006, which were documented in NRC Inspection Report 05000528; 05000529; 05000530/2006012 (ADAMS Reference ML063400561). The underlying performance deficiencies involved a failure to establish appropriate instructions for performing corrective maintenance activities on a K-1

relay and the failure to identify and correct the cause of erratic K-1 relay operation prior to installation of the relay into the Unit 3, Train A emergency diesel generator voltage regulator circuit. In accordance with NRC Manual Chapter 0305, "Operating Reactor Assessment Program," the decision to place Unit 3 in the Multiple/Repetitive Degraded Cornerstone column was made on the basis of the definition of a Repetitive Degraded Cornerstone in that there are two separate safety significant inspection findings (one Yellow and one White) in the Mitigating Systems cornerstone and the cornerstone has been degraded for more than four quarters.

The Yellow finding for all three units has remained open since the fourth quarter of 2004 because problems with corrective action scope and effectiveness were identified during two NRC supplemental inspections. During the first inspection, which was conducted in late 2005, we determined that Arizona Public Service Company (APS) had performed an adequate root cause evaluation of the design control problem; however, there were a number of problems, involving corrective action scope, effectiveness, and monitoring/verification measures. During the second supplemental inspection, the onsite portion of which was completed the week of July 24, 2006, we determined that the corrective actions taken in response to the root causes and related programmatic concerns involving questioning attitude, technical rigor, and operability determinations had not been fully effective. We also concluded that the performance monitoring measures (e.g., metrics) necessary to fully assess the effectiveness of the corrective actions within these areas did not take into account all the relevant data. Subsequent to this second supplemental inspection of the Yellow finding, the NRC completed two special inspections in the second half of 2006 involving the chemical fouling of the ultimate heat sink affecting all three units and an inoperable Unit 3 emergency diesel generator which resulted in the White finding discussed above. The causes of the findings associated with these inspections are similar to the findings from the supplemental inspections of the Yellow finding, as well as other performance deficiencies identified by our baseline inspections.

Since 2005, APS has indicated on two occasions that the actions taken in response to the Yellow finding were sufficient to support closure of the finding. As noted above, we determined that APS's actions taken at the time of both inspections were not sufficient to support closure of the finding. In fact, APS's internal reviews conducted before each NRC inspection indicated that the finding was not ready to be closed. The lack of readiness for these supplemental inspections, the results of our second inspection of the effectiveness of the corrective actions in response to the Yellow finding and APS's progress in implementing its improvement initiatives were discussed during a public meeting on September 7, 2006. As a result of that meeting and followup reviews, APS revised its actions in response to the Yellow finding as discussed in APS's letter dated November 16, 2006 (ADAMS Reference ML063320163).

Because the Yellow and White findings in the Mitigating Systems cornerstone have resulted in Unit 3 being assessed in the Multiple/Repetitive Degraded Cornerstone column of the NRC's Action Matrix, additional regulatory oversight actions will be implemented at your facility. These actions could include: (1) conducting supplemental inspections of the individual and collective issues; (2) issuing a confirmatory action letter to document APS's commitments stemming from its performance improvement plan (or other actions, as warranted); and (3) conducting public meetings to discuss progress in implementing your improvement initiatives.

Consistent with NRC Manual Chapter 0305, the NRC will conduct an Inspection Procedure 95001 supplemental inspection, "Inspection For One Or Two White Inputs In A Strategic Performance Area"; another followup Inspection Procedure 95002 supplemental inspection, "Inspection For One Degraded Cornerstone Or Any Three White Inputs In a Strategic Performance Area"; and an Inspection Procedure 95003, "Supplemental Inspection for Repetitive Degraded Cornerstones, Multiple Degraded Cornerstones, Multiple Yellow Inputs, or One Red Input," following notification from you on your readiness to support these inspections. The 95001 and 95002 supplemental inspections may be performed independently or as part of the 95003 inspection. The objectives of these inspections are described in detail in the individual inspection procedures, which are publicly available.

For the fifth consecutive assessment letter since March 2, 2005, we have advised you of substantive crosscutting issues in the areas of human performance and problem identification and resolution. The NRC identified 25 Green findings and one example of a White finding with crosscutting aspects in the human performance area. These findings involved the Initiating Events, Mitigating Systems, and Occupational Radiation Safety cornerstones. Crosscutting themes were identified in the area components involving decision-making (instances of ineffective communication of decisions to personnel); resources (instances of inadequate procedures and instructions); and work practices (instances of ineffective human error prevention techniques and instances of not following procedures). Examples include: multiple instances of failing to comply with Technical Specification requirements during the process of unit startup; instances of failing to perform technically adequate operability determinations for degraded and nonconforming conditions of safety-related systems and components; instances of failing to follow procedures which resulted in consequential plant impacts; and instances of failing to use other appropriate error prevention techniques which resulted in inappropriate system configurations, as well as other unintended, consequential impacts on plant systems and components.

Eleven examples of Green findings and one example of a White finding were identified in the corrective action component of the problem identification and resolution crosscutting area. These findings involved the Mitigating Systems and Emergency Preparedness cornerstones. Crosscutting themes identified in this component involved inadequate evaluations of problems or degraded conditions and untimely implementation of corrective actions. Many of the findings involved instances of treating the symptoms rather than identifying the causes, a lack of technical rigor in assessing problems, not adequately determining the extent of the problems when they were identified, and not correcting problems. These performance deficiencies have resulted in long-standing, degraded safety-related systems and components; repetitive events and conditions; latent failures of safety-related equipment; and insufficiently controlled work instructions.

Previous NRC assessments of your safety performance noted communication problems between your operations and engineering organizations, particularly with respect to evaluating problems within the context of the operability determination process. Some of the findings identified during 2006 also suggest program implementation and interface problems in other parts of the PVNGS organization (e.g., the chemistry and maintenance organizations).

During the assessment period, the NRC performed periodic inspections of your corrective actions to address both substantive crosscutting issues. Throughout 2006, the results of our inspections consistently determined that APS took some corrective actions to address these issues; however, the actions were not completely effective, were still being developed, or were only partially implemented. This is the same performance status noted in our March 2 and August 31, 2006, assessment letters. During the September 7, 2006, meeting, we also discussed APS's progress in implementing corrective actions in response to these substantive crosscutting issues as they relate to APS's Integrated Improvement Plan. In two letters dated December 8, 2006 (ADAMS Reference ML070300805 and ML070300817), APS described the actions being taken or planned to close the substantive crosscutting issues. In these letters, APS also indicated it would notify the NRC of the PVNGS staff's readiness to support NRC closure of these issues. Accordingly, we will monitor your improvement efforts through the baseline inspection program and perform a detailed assessment following your notification of readiness for closure verification. These substantive crosscutting issues will remain open until we determine that your corrective actions have resulted in improved performance.

As described in NRC Manual Chapter 0305, following the third consecutive assessment letter identifying the same substantive crosscutting issue with the same crosscutting theme, the NRC may request that the licensee perform an assessment of its safety culture. We understand that APS plans to complete an independent safety culture assessment in May 2007. We request that your staff discuss the scope of this safety culture assessment with the NRC before commencing the activity. The NRC will review the results of the safety culture assessment before initiating the Inspection Procedure 95003 inspection activity. Additionally, you are requested to address the substantive crosscutting issues during the annual assessment meeting. The meeting date and discussion topics will be provided by separate correspondence.

The enclosed inspection plan details the inspections, except those related to physical protection, scheduled through September 30, 2008. In addition to the baseline inspections, the NRC will be implementing Inspection Procedure 50001, "Steam Generator Replacement Inspection," relative to the planned replacement of the Unit 3 steam generators and Temporary Instruction 2515/166, "Pressurized Water Reactor Containment Sump Blockage," in Units 1 and 3. The NRC will also conduct the supplemental inspections that were previously discussed. The inspection plan is provided to allow for the resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last 9 months of the inspection plan are tentative and may be revised at the midcycle review.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact Rebecca Nease at (817) 860-8250 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

Bruce S. Mallett

Regional Administrator

Dockets: 50-528

50-529 50-530

Licenses: NPF-41

NPF-51 NPF-74

Enclosure:

Palo Verde Inspection/Activity Plan

cc w/enclosure:

Steve Olea Arizona Corporation Commission 1200 W. Washington Street Phoenix, AZ 85007

Douglas K. Porter, Senior Counsel Southern California Edison Company Law Department, Generation Resources P.O. Box 800 Rosemead, CA 91770

Chairman
Maricopa County Board of Supervisors
301 W. Jefferson, 10th Floor
Phoenix, AZ 85003

Aubrey V. Godwin, Director Arizona Radiation Regulatory Agency 4814 South 40 Street Phoenix, AZ 85040 Scott Bauer, Acting General Manager Regulatory Affairs and Performance Improvement Palo Verde Nuclear Generating Station Mail Station 7636 P.O. Box 52034 Phoenix, AZ 85072-2034

Jeffrey T. Weikert Assistant General Counsel El Paso Electric Company Mail Location 167 123 W. Mills El Paso, TX 79901

John W. Schumann Los Angeles Department of Water & Power Southern California Public Power Authority P.O. Box 51111, Room 1255-C Los Angeles, CA 90051-0100 John Taylor Public Service Company of New Mexico 2401 Aztec NE, MS Z110 Albuquerque, NM 87107-4224

Geoffrey M. Cook Southern California Edison Company 5000 Pacific Coast Hwy, Bldg. N50 San Clemente, CA 92672

Robert Henry Salt River Project 6504 East Thomas Road Scottsdale, AZ 85251

Brian Almon
Public Utility Commission
William B. Travis Building
P.O. Box 13326
1701 North Congress Avenue
Austin, TX 78701-3326

Karen O'Regan Environmental Program Manager City of Phoenix Office of Environmental Programs 200 West Washington Street Phoenix, AZ 85003

Matthew Benac Assistant Vice President Nuclear & Generation Services El Paso Electric Company 340 East Palm Lane, Suite 310 Phoenix, AZ 85004

Chief, Radiological Emergency Preparedness Section Oakland Field Office Chemical and Nuclear Preparedness and Protection Division Department of Homeland Security 1111 Broadway, Suite 1200 Oakland, CA 94607-4052 Louis Trammell, Director Arizona Division of Emergency Management 5636 East McDowell Road Building 101 Phoenix, AZ 85008-3495

Nancy Ward, Regional Director Federal Emergency Management Agency Region IX 1111 Broadway, Suite 1200 Oakland, CA 94607-4052

The Honorable Marie Lopez-Rogers Mayor of Avondale 11465 W. Civic Center Drive, Suite 280 Avondale, AZ 85323

The Honorable Bobby Bryant Mayor of Buckeye 100 North Apache Road Buckeye, AZ 85326

The Honorable Fred Waterman Mayor of El Mirage P.O. Box 26 El Mirage, AZ 85335

The Honorable Elaine Scruggs Mayor of Glendale 5850 West Glendale Avenue Glendale, AZ 85301

The Honorable James M. Cavanaugh Mayor of Goodyear 119 North Litchfield Road Goodyear, AZ 85338

The Honorable Tom Shoaf Mayor of Litchfield 244 West Wigwam Blvd. Litchfield Park, AZ 85340

The Honorable John Keegan Mayor of Peoria 8401 West Monroe Street Peoria, AZ 85345 The Honorable Phil Gordon Mayor of Phoenix Phoenix City Hall 200 West Washington Phoenix, AZ 85007

The Honorable Joan Shafer Mayor of Surprise 12425 West Bell Road Surprise, AZ 85374

The Honorable Adolfo Gamez Mayor of Tolleson 9555 West Van Buren Street Tolleson, AZ 85353

The Honorable Michael LeVault Mayor of Youngtown 12030 Clubhouse Square Youngtown, AZ 85363

Robin Berry Palo Verde School District P.O. Box 108 Palo Verde, AZ 85343

Chad Turner, Superintendent Arlington Elementary School District 9410 S. 355th Avenue Arlington, AZ 85322

Carter Gable
Arlington Canal Company
P.O. Box 150
Arlington, AZ 85322

Doris Heisler Tonopah Valley Association 3002 N. 423rd Avenue Tonopah, AZ 85354

Lyle King Buckeye Farmer P.O. Box 224 Buckeye, AZ 85322 Chris Larson Arlington CATS Club P.O. Box 194 Arlington, AZ 85322

Grace Molina Arlington Hispanic Community 910 n. 343rd Avenue Tonopah, AZ 85354

Les Meredith Arlington Lions Club P.O. Box 69 Arlington, AZ 85322

Pam Miller HC03 Box 85 Palo Verde, AZ 85343

Neil Peters P.O. Box 57 Arlington, AZ 85322

Paul Roetto Friends of Saddle Mountain 3708 N. 339th Avenue Tonopah, AZ 85354

Roxanne Morris Ruth Fisher Unified School District 38201 W. Indian School Road Tonopah, AZ 85354

Judy Shaw 20 N. 350th Avenue Tonopah, AZ 85354

Robert Hathaway TVCC 37705 W. Buckeye Road Tonopah, AZ 85354

Jack Arend Tonopah Valley Community Council P.O. Box 874 Tonopah, AZ 85354 Melba Jury 33228 W. Sunland Avenue Tonopah, AZ 85354

Andy Jacobs Office of U.S. Senator Jon Kyl 2200 E. Camelback Road, Suite 120 Phoenix, AZ 85016

Carlos Sierra Office of U.S. Senator John McCain 5353 North 16th Street, Suite 105 Phoenix, AZ 85016

Ruben H. Reyes, District Director Office of U.S. Congressman Raul Grijalva 810 E. 22nd Street, Suite 102 Tucson, AZ 85713

Sheriff Joe Arpaio 100 West Washington, Suite 1900 Phoenix, AZ 85003

Fulton Brock, Supervisor, District 1 Board of Supervisors 301 W. Jefferson Phoenix, AZ 85003

Don Stapley, Supervisor, District 2 Board of Supervisors 301 W. Jefferson Phoenix, AZ 85003

Andrew Kunasek, Supervisor, District 3 Board of Supervisors 301 W. Jefferson Phoenix, AZ 85003

Max W. Wilson, Supervisor, District 4 Board of Supervisors 301 W. Jefferson Phoenix, AZ 85003

Mary Rose Wilcox, Supervisor, District 5 Board of Supervisors 301 W. Jefferson Phoenix, AZ 85003 State Representative Manuel V. Alvarez Arizona House of Representatives 1700 W. Washington Room 129 Phoenix, AZ 85007

State Senator Marsha Arzberger Arizona Senate 1700 W. Washington Room 213 Phoenix, AZ 85007

Institute of Nuclear Power Operations (INPO) Records Center 700 Galleria Parkway SE, Suite 100 Atlanta, GA 30339 Page 1 of 2

02/21/2007

13:24:52

Palo Verde 1 **Inspection / Activity Plan**

Report 22

01/01/2007 - 09/30/2008

Unit				No. of Staff	Planned	d Dates	Inspection
Number	Inspection Ac	tivity	Title	on Site	Start	End	Type
Petrol Extraordistance of American Control	RP-ORS -	OCCUP	ATIONAL RADIATION SAFETY	1			
1	IP 7112101		Access Control to Radiologically Significant Areas		01/08/2007	01/12/2007	Baseline Inspections
1	IP 7112102		ALARA Planning and Controls		01/08/2007	01/12/2007	Baseline Inspections
1	IP 71151		Performance Indicator Verification		01/08/2007	01/12/2007	Baseline Inspections
	EB2-52B -	PIR INS	PECTION	11			
1	IP 71152B		Identification and Resolution of Problems		01/22/2007	01/26/2007	Baseline Inspections
1	IP 71152B		Identification and Resolution of Problems		02/05/2007	02/09/2007	Baseline Inspections
	RP TEAM -	RADIAT	TION SAFETY TEAM	5			
1	IP 7112103		Radiation Monitoring Instrumentation and Protective Equipment		01/29/2007	02/02/2007	Baseline Inspections
1	IP 7112201		Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		01/29/2007	02/02/2007	Baseline Inspections
1	IP 7112202		Radioactive Material Processing and Transportation		01/29/2007	02/02/2007	Baseline Inspections
1	IP 7112203		Radiological Environmental Monitoring Program (REMP) And Radioactive Material Control F		01/29/2007	02/02/2007	Baseline Inspections
	EB1-21 -	CDB		8			
1	IP 7111121		Component Design Bases Inspection		02/26/2007	03/02/2007	Baseline Inspections
1	IP 7111121		Component Design Bases Inspection		03/12/2007	03/23/2007	Baseline Inspections
	EP1 -	· PV EP I	EXERCISE	4			
1	IP 7111401		Exercise Evaluation		03/05/2007	03/09/2007	Baseline Inspections
1	IP 7111404		Emergency Action Level and Emergency Plan Changes		03/05/2007	03/09/2007	Baseline Inspections
1	IP 71151		Performance Indicator Verification		03/05/2007	03/09/2007	Baseline Inspections
	EB1-08P -	· ISI U1 8		1			
1	IP 2515/166		Pressurized Water Reactor Containment Sump Blockage [NRC GENERIC LETTER 2004-02		05/21/2007	06/01/2007	Safety Issues
1	IP 7111108P		Inservice Inspection Activities - PWR		05/21/2007	06/01/2007	Baseline Inspections
	EXAM -	· INITIAL	EXAM	4			
1	X02351		PV UNIT 1 - INITIAL EXAM (08/07)		07/09/2007	07/13/2007	Not Applicable
1	X02351		PV UNIT 1 - INITIAL EXAM (08/07)		07/23/2007	07/27/2007	Not Applicable
	EB2-05T -	· TRIENN	IIAL FIRE PROTECTION	4			
1	IP 7111105T		Fire Protection [Triennial]		07/23/2007	07/27/2007	Baseline Inspections
1	IP 7111105T		Fire Protection [Triennial]		08/13/2007	08/17/2007	Baseline Inspections
	RP-ORS4 -	OCCUP	PATIONAL RADIATION SAFETY-ACCESS	1			
1	IP 7112101		Access Control to Radiologically Significant Areas		10/21/2007	10/21/2007	Baseline Inspections
1 .	IP 7112102		ALARA Planning and Contrels		10/21/2007	10/21/2007	Baseline Inspections
1	IP 71151		Performance Indicator Verification		10/21/2007	10/21/2007	Baseline Inspections
	RP-ORS5 -		ATIONAL RADIATION SAFETY-ALARA	1			
1	IP 7112101		Access Control to Radiologically Significant Areas		11/26/2007	11/30/2007	Baseline Inspections
1	IP 7112102		ALARA Planning and Controls		11/26/2007	11/30/2007	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Page 2 of 2

02/21/2007 13:24:52

Report 22

Palo Verde 1

Inspection / Activity Plan 01/01/2007 - 09/30/2008

Unit			No. of Staff	Planne		Inspection
Number	Inspection Activity	Title	on Site	Start	End	Type
	RP-ORS5 - OCCU	PATIONAL RADIATION SAFETY-ALARA	1			
1	IP 71151	Performance Indicator Verification		11/26/2007	11/30/2007	Baseline Inspections
	EP2 - EP PR	OGRAM	1			
1	IP 7111402	Alert and Notification System Testing		02/11/2008	02/15/2008	Baseline Inspections
1	IP 7111403	Emergency Response Organization Augmentation Testing		02/11/2008	02/15/2008	Baseline Inspections
1	IP 7111404	Emergency Action Level and Emergency Plan Changes		02/11/2008	02/15/2008	Baseline Inspections
1	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		02/11/2008	02/15/2008	Baseline Inspections
1	IP 71151	Performance Indicator Verification		02/11/2008	02/15/2008	Baseline Inspections
	RP-ORS1 - OCCU	PATIONAL RADIATION SAFETY - ALARA	1			
1	IP 7112101	Access Control to Radiologically Significant Areas		02/11/2008	02/15/2008	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		02/11/2008	02/15/2008	Baseline Inspections
1	IP 71151-PR01	RETS/ODCM Radiological Effluent		02/11/2008	02/15/2008	Baseline Inspections
	EB2-07B - BIENN	IIAL HEAT SINK INSPECTION	,1			
1	IP 7111107B	Heat Sink Performance		02/25/2008	02/29/2008	Baseline Inspections
	RP-ORS2 - OCCU	PATIONAL RADIATION SAFETY - ACCESS	1			
1	IP 7112101	Access Control to Radiologically Significant Areas		04/28/2008	05/02/2008	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		04/28/2008	05/02/2008	Baseline Inspections
1	IP 71151-OR01	Occupational Exposure Control Effectiveness		04/28/2008	05/02/2008	Baseline Inspections
	EB2-52B - BIENN	IIAL PI&R INSPECTION	1			
1	IP 71152B	Identification and Resolution of Problems		06/09/2008	06/13/2008	Baseline Inspections
1	IP 71152B	Identification and Resolution of Problems		06/23/2008	06/27/2008	Baseline Inspections
	EB2-12T - TRIEN	NIAL MAINTENANCE RULE INSPECTION	1			
1	IP 7111112B	Maintenance Effectiveness		07/21/2008	07/25/2008	Baseline Inspections
	EB1-21 - CDBI		6			
1	IP 7111121	Component Design Bases Inspection		08/11/2008	08/15/2008	Baseline Inspections
1	IP 7111121	Component Design Bases Inspection		08/25/2008	09/05/2008	Baseline Inspections
	RP-ORS3 - OCCU	PATIONAL RADIATION SAFETY - ALARA	1			
1	IP 7112101	Access Control to Radiologically Significant Areas		09/29/2008	10/03/2008	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		09/29/2008	10/03/2008	Baseline Inspections
1	IP 71151-OR01	Occupational Exposure Control Effectiveness		09/29/2008	10/03/2008	Baseline Inspections

Page 1 of 2

02/21/2007 13:25:02

Report 22

Palo Verde 2 Inspection / Activity Plan 01/01/2007 - 09/30/2008

No. of Staff Unit Planned Dates Inspection on Site Start Fnd Tvpe Number Inspection Activity Title - OCCUPATIONAL RADIATION SAFETY 1 RP-ORS 2 IP 7112101 01/08/2007 01/12/2007 Baseline Inspections Access Control to Radiologically Significant Areas 01/12/2007 Baseline Inspections 2 IP 7112102 ALARA Planning and Controls 01/08/2007 01/08/2007 01/12/2007 Baseline Inspections 2 IP 71151 Performance Indicator Verification - PIR INSPECTION 11 FB2-52B 2 IP 71152B Identification and Resolution of Problems 01/22/2007 01/26/2007 Baseline Inspections 2 IP 71152B Identification and Resolution of Problems 02/05/2007 02/09/2007 Baseline Inspections 5 **RP TEAM** - RADIATION SAFETY TEAM 01/29/2007 02/02/2007 Baseline Inspections 2 IP 7112103 Radiation Monitoring Instrumentation and Protective Equipment 2 Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems 01/29/2007 02/02/2007 Baseline Inspections IP 7112201 2 IP 7112202 Radioactive Material Processing and Transportation 01/29/2007 02/02/2007 Baseline Inspections 02/02/2007 Baseline Inspections 2 IP 7112203 Radiological Environmental Monitoring Program (REMP) And Radioactive Material Control F 01/29/2007 EB1-21 - CDB 8 02/26/2007 03/02/2007 Baseline Inspections IP 7111121 Component Design Bases Inspection 2 IP 7111121 Component Design Bases Inspection 03/12/2007 03/23/2007 Baseline Inspections 2 FP1 - PV FP EXERCISE 4 03/05/2007 03/09/2007 Baseline Inspections 2 IP 7111401 Exercise Evaluation Emergency Action Level and Emergency Plan Changes 03/05/2007 03/09/2007 Baseline Inspections 2 IP 7111404 2 IP 71151 Performance Indicator Verification 03/05/2007 03/09/2007 Baseline Inspections **EXAM** - INITIAL EXAM 4 07/13/2007 X02352 PV UNIT 2 - INITIAL EXAM (08/07) 07/09/2007 Not Applicable 2 07/23/2007 07/27/2007 Not Applicable 2 X02352 PV UNIT 2 - INITIAL EXAM (08/07) 4 **EB2-05T** - TRIENNIAL FIRE PROTECTION 07/23/2007 07/27/2007 Baseline Inspections 2 IP 7111105T Fire Protection [Triennial] 08/13/2007 08/17/2007 Baseline Inspections 2 IP 7111105T Fire Protection [Triennial] RP-ORS4 - OCCUPATIONAL RADIATION SAFETY-ACCESS 1 10/21/2007 10/21/2007 Baseline Inspections 2 IP 7112101 Access Control to Radiologically Significant Areas 2 IP 7112102 **ALARA Planning and Controls** 10/21/2007 10/21/2007 Baseline Inspections 10/21/2007 10/21/2007 Baseline Inspections 2 IP 71151 Performance Indicator Verification RP-ORS5 - OCCUPATIONAL RADIATION SAFETY-ALARA 1 11/26/2007 11/30/2007 Baseline Inspections 2 IP 7112101 Access Control to Radiologically Significant Areas 11/30/2007 2 IP 7112102 **ALARA Planning and Controls** 11/26/2007 Baseline Inspections 2 11/26/2007 11/30/2007 Baseline Inspections IP 71151 Performance Indicator Verification EP2 - EP PROGRAM 1 02/15/2008 Baseline Inspections 2 IP 7111402 02/11/2008 Alert and Notification System Testing

This report does not include INPO and OUTAGE activities.

This report shows only on-site and announced inspection procedures.

Page 2 of 2

02/21/2007 13:25:02

Report 22

Palo Verde 2 Inspection / Activity Plan 01/01/2007 - 09/30/2008

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Start	I Dates End	Inspection Type
Number			1			L _{province} and the second
_	EP2 - EP PR		•	00/44/0000	00/45/0000	Describes Increations
2	IP 7111403	Emergency Response Organization Augmentation Testing		02/11/2008	02/15/2008	Baseline Inspections
2	IP 7111404	Emergency Action Level and Emergency Plan Changes		02/11/2008	02/15/2008	Baseline Inspections
2	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		02/11/2008	02/15/2008	Baseline Inspections
2	IP 71151	Performance Indicator Verification		02/11/2008	02/15/2008	Baseline Inspections
	RP-ORS1 - OCCUI	PATIONAL RADIATION SAFETY - ALARA	1			
2	IP 7112101	Access Control to Radiologically Significant Areas		02/11/2008	02/15/2008	Baseline Inspections
2	IP 7112102	ALARA Planning and Controls		02/11/2008	02/15/2008	Baseline Inspections
2	IP 71151-OR01	Occupational Exposure Control Effectiveness		02/11/2008	02/15/2008	Baseline Inspections
	EB2-07B - BIENN	IAL HEAT SINK INSPECTION	1			
2	IP 7111107B	Heat Sink Performance		02/25/2008	02/29/2008	Baseline Inspections
	EB1-08U2 - INSER	VICE INSPECTION ACTIVITIES PV U2	1			
2	IP 7111108P	Inservice Inspection Activities - PWR		04/07/2008	04/25/2008	Baseline Inspections
	RP-ORS2 - OCCUI	PATIONAL RADIATION SAFETY - ACCESS	1			
2	IP 7112101	Access Control to Radiologically Significant Areas		04/28/2008	05/02/2008	Baseline Inspections
2	IP 7112102	ALARA Planning and Controls		04/28/2008	05/02/2008	Baseline Inspections
	EB2-52B - BIENN	IAL PI&R INSPECTION	1			
2	IP 71152B	Identification and Resolution of Problems		06/09/2008	06/13/2008	Baseline Inspections
2	IP 71152B	Identification and Resolution of Problems		06/23/2008	06/27/2008	Baseline Inspections
	EB2-12T - TRIEN	NIAL MAINTENANCE RULE INSPECTION	1			
2	IP 7111112B	Maintenance Effectiveness		07/21/2008	07/25/2008	Baseline Inspections
	EB1-21 - CDBI		6			
2	IP 7111121	Component Design Bases Inspection		08/11/2008	08/15/2008	Baseline Inspections
2	IP 7111121	Component Design Bases Inspection		08/25/2008	09/05/2008	Baseline Inspections
	RP-ORS3 - OCCUI	PATIONAL RADIATION SAFETY - ALARA	1			
2	IP 7112101	Access Control to Radiologically Significant Areas		09/29/2008	10/03/2008	Baseline Inspections
2	IP 7112102	ALARA Planning and Controls		09/29/2008	10/03/2008	Baseline Inspections
2	IP 71151-PR01	RETS/ODCM Radiological Effluent		09/29/2008	10/03/2008	Baseline Inspections

Page 1 of 2

02/21/2007 13:25:17

Report 22

Palo Verde 3 Inspection / Activity Plan

01/01/2007 - 09/30/2008

Unit				No. of Staff		d Dates	Inspection
Number	Inspection A	ctivity	Title	on Site	Start	End	Type
and the state of t	SG REP	- U3 SG	REPLACEMENT ACTIVITIES	1			
3	IP 50001		Steam Generator Replacement Inspection		01/01/2007	12/31/2007	Other Routine
	RP-ORS	- OCCUP	PATIONAL RADIATION SAFETY	1			
3	IP 7112101		Access Control to Radiologically Significant Areas		01/08/2007	01/12/2007	Baseline Inspections
3	IP 7112102		ALARA Planning and Controls		01/08/2007	01/12/2007	Baseline Inspections
3	IP 71151		Performance Indicator Verification		01/08/2007	01/12/2007	Baseline Inspections
	EB2-52B	- PIR INS	SPECTION STATE OF THE PROPERTY	11			
3	IP 71152B		Identification and Resolution of Problems		01/22/2007	01/26/2007	Baseline Inspections
3	IP 71152B		Identification and Resolution of Problems		02/05/2007	02/09/2007	Baseline Inspections
	RP TEAM	- RADIA	TION SAFETY TEAM	5			
3	IP 7112103		Radiation Monitoring Instrumentation and Protective Equipment		01/29/2007	02/02/2007	Baseline Inspections
3	IP 7112201		Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		01/29/2007	02/02/2007	Baseline Inspections
3	IP 7112202		Radioactive Material Processing and Transportation		01/29/2007	02/02/2007	Baseline Inspections
3	IP 7112203		Radiological Environmental Monitoring Program (REMP) And Radioactive Material Control F		01/29/2007	02/02/2007	Baseline Inspections
	EB1-21	- CDB		8			
3	IP 7111121		Component Design Bases Inspection		02/26/2007	03/02/2007	Baseline Inspections
3	IP 7111121		Component Design Bases Inspection		03/12/2007	03/23/2007	Baseline Inspections
	EP1	- PV EP	EXERCISE	4			
3	IP 7111401		Exercise Evaluation		03/05/2007	03/09/2007	Baseline Inspections
3	IP 7111404		Emergency Action Level and Emergency Plan Changes		03/05/2007	03/09/2007	Baseline Inspections
3	IP 71151		Performance Indicator Verification		03/05/2007	03/09/2007	Baseline Inspections
	EXAM	- INITIAL	EXAM	4			
3	X02353		PV UNIT 3 - INITIAL EXAM (08/07)		07/09/2007	07/13/2007	Not Applicable
3	X02353		PV UNIT 3 - INITIAL EXAM (08/07)		07/23/2007	07/27/2007	Not Applicable
	EB2-05T	- TRIENN	NAL FIRE PROTECTION	4			
3	IP 7111105T	•	Fire Protection [Triennial]		07/23/2007	07/27/2007	Baseline Inspections
3	IP 7111105T	•	Fire Protection [Triennial]		08/13/2007	08/17/2007	Baseline Inspections
	EB1-08P	- ISI U3 8	≩ TI 166	1			
3	IP 2515/166		Pressurized Water Reactor Containment Sump Blockage [NRC GENERIC LETTER 2004-02		10/01/2007	10/12/2007	Safety Issues
3	IP 7111108P	•	Inservice Inspection Activities - PWR		10/01/2007	10/12/2007	Baseline Inspections
	RP-ORS4	- OCCUP	PATIONAL RADIATION SAFETY-ACCESS	1			
3	IP 7112101		Access Control to Radiologically Significant Areas		10/21/2007	10/21/2007	Baseline Inspections
3	IP 7112102		ALARA Planning and Controls		10/21/2007	10/21/2007	Baseline Inspections
3	IP 71151		Performance Indicator Verification		10/21/2007	10/21/2007	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Page 2 of 2

02/21/2007 13:25:17

Report 22

Palo Verde 3

Inspection / Activity Plan 01/01/2007 - 09/30/2008

Unit	p=		No. of Staff	Planned		Inspection
Number	Inspection Activity	Title	on Site	Start	End	Type
	RP-ORS5 - OCCL	JPATIONAL RADIATION SAFETY-ALARA	1			
3	IP 7112101	Access Control to Radiologically Significant Areas		11/26/2007	11/30/2007	Baseline Inspections
3	IP 7112102	ALARA Planning and Controls		11/26/2007	11/30/2007	Baseline Inspections
3	IP 71151	Performance Indicator Verification		11/26/2007	11/30/2007	Baseline Inspections
	EP2 - EP PF	ROGRAM	1			
3	IP 7111402	Alert and Notification System Testing		02/11/2008	02/15/2008	Baseline Inspections
3	IP 7111403	Emergency Response Organization Augmentation Testing		02/11/2008	02/15/2008	Baseline Inspections
3	IP 7111404	Emergency Action Level and Emergency Plan Changes		02/11/2008	02/15/2008	Baseline Inspections
3	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		02/11/2008	02/15/2008	Baseline Inspections
3	IP 71151	Performance Indicator Verification		02/11/2008	02/15/2008	Baseline Inspections
	RP-ORS1 - OCCL	JPATIONAL RADIATION SAFETY - ALARA	1			
3	IP 7112101	Access Control to Radiologically Significant Areas		02/11/2008	02/15/2008	Baseline Inspections
3	IP 7112102	ALARA Planning and Controls		02/11/2008	02/15/2008	Baseline Inspections
3	IP 71151-OR01	Occupational Exposure Control Effectiveness		02/11/2008	02/15/2008	Baseline Inspections
	EB2-07B - BIENI	NIAL HEAT SINK INSPECTION	1			
3	IP 7111107B	Heat Sink Performance		02/25/2008	02/29/2008	Baseline Inspections
	RP-ORS2 - OCCL	JPATIONAL RADIATION SAFETY - ACCESS	1			
3	IP 7112101	Access Control to Radiologically Significant Areas		04/28/2008	05/02/2008	Baseline Inspections
3	IP 7112102	ALARA Planning and Controls		04/28/2008	05/02/2008	Baseline Inspections
3	IP 71151-PR01	RETS/ODCM Radiological Effluent		04/28/2008	05/02/2008	Baseline Inspections
	EB2-52B - BIENI	NIAL PI&R INSPECTION	1			
3	IP 71152B	Identification and Resolution of Problems		06/09/2008	06/13/2008	Baseline Inspections
3	IP 71152B	Identification and Resolution of Problems		06/23/2008	06/27/2008	Baseline Inspections
	EB2-12T - TRIEN	NNIAL MAINTENANCE RULE INSPECTION	1			
3	IP 7111112B	Maintenance Effectiveness		07/21/2008	07/25/2008	Baseline Inspections
	EB1-21 - CDBI		6			
3	IP 7111121	Component Design Bases Inspection		08/11/2008	08/15/2008	Baseline Inspections
3	IP 7111121	Component Design Bases Inspection		08/25/2008	09/05/2008	Baseline Inspections
	RP-ORS3 - OCCU	JPATIONAL RADIATION SAFETY - ALARA	1			
3	IP 7112101	Access Control to Radiologically Significant Areas		09/29/2008	10/03/2008	Baseline Inspections
3	IP 7112102	ALARA Planning and Controls		09/29/2008	10/03/2008	Baseline Inspections

Electronic distribution by RIV:
Regional Administrator (BSM1)
DRP Director (ATH)
DRS Director (DDC)
DRS Deputy Director (RJC1)
Senior Resident Inspector (GXW2)
Branch Chief, DRP/D (RLN1)
Senior Project Engineer, DRP/D (GEW)
Team Leader, DRP/TSS (FLB2)
RITS Coordinator (MSH3)
V. Dricks, PAO (VLD)
W. Maier, RSLO (WAM)
L. Owen, RA Secretary (LAO)
DRS Branch Chiefs (WBJ, ATG, LJS, MPS1)
C. Miller, Chief, TRPS, OEDO (CGM)
S. Richards, Deputy Director, DIRS, NRR (SAR
J. Lubinski, Deputy Director, DORL, NRR (JWL
C. Haney, Director, DORL, NRR (CXH)
D. Terao, Chief, PLB IV, DORL, NRR (DXT)
M. Fields, NRR Project Manager (MBF1)
RidsNrrDirs1pab@nrc.gov
ROPreports@nrc.gov

SUNSI Review Completed:			Initials:ath ⊠ Non-Sensitive
R:_REACTORS\EOC and	Midcycle\EOC Asses	sment Letters\2006 - c	lated 3-2-07\PV.wpd
RIV:C:DRP/D	D:DRS	D:DRP	DRA
RLNease;df	DDChamberlain	ATHowell III	TPGwynn
/RA/	/RA/	/RA/	BSMallett for
2/26/07	2/26/07	2/26/07	3/2/07
RA			
BSMallett			
/RA/			
3/2/07			
OFFICIAL RECORD COPY	,	T=Telephone	E=E-mail F=Fax