

Originator: CONVERTED DATA**Originator Phone:** 0**Originator Group:** CONVERTED DATA**Operability Required:** N**Supervisor Name:** CONVERTED DATA**Reportability Required:** N**Discovered Date:** 03/26/1999 00:00**Initiated Date:** 03/26/1999 00:00**Condition Description:**

NCR 99-19 FOR 2 LOOSE 2" DIA. TORUS ANCHOR BOLT EXTENSIONS AT TORUS SADDLE SUPPORT
BETWEEN BAYS 12 & 13 AND CORROSION OF BASEPLATES EXCEEDING 10% OF BASE METAL THICKNESS.

Immediate Action Description:**Suggested Action Description:****EQUIPMENT:**Tag NameTag Suffix Name Component Code Process System Code

50

REFERENCE ITEMS:Type CodeDescription

CONVERTED PR

PR.99.9102

Entergy

ADMIN

CR-PNP-1999-09102

Initiated Date: 3/26/1999 0:00

Owner Group :Eng DE Mech Civil Struct Staff

Current Contact: SHATAS, A.

Current Significance: C - CORRECTION

Closed by: SHATAS, A.

4/2/1999 0:00

Summary Description:

NCR 99-19 FOR 2 LOOSE 2" DIA. TORUS ANCHOR BOLT EXTENSIONS AT TORUS SADDLE SUPPORT BETWEEN BAYS 12 & 13 AND CORROSION OF BASEPLATES EXCEEDING 10% OF BASE METAL THICKNESS.

Remarks Description:

PR=EF

NCR 99-19 TORUS ANCHOR BOLTS BASE METAL

-SUPPORT-

Closure Description:

EVALUATION AND CORRECTIVE ACTION COMPLETE.