

May 3, 2007

NOTE TO FILE:

The pictures on the following pages were sent to me by Marc Ferdas, Senior Resident Inspector at Oyster Creek Generating Station on May 2, 2007.

The four pictures show the condition of the trenches in the "as found" condition during a walkdown of the Oyster Creek Drywell at the start of a Maintenance outage on April 29, 2007. Both trenches were found to be dry with no evidence of water present. The digital pictures were made by Ryan Treadway, Resident Inspector at Oyster Creek.

The walkdown is part of the drywell inspection conducted by the NRC Inspectors at Oyster Creek. The results of the inspection will be included in the Inspection Report 2007-003 to be produced later this year.

The email forwarding the pictures to me and the Email from Mr. Treadway to Mr. Ferdas will be placed into ADAMS and added to the package containing this note.

/RA/

Donnie J. Ashley  
NRR/DLR/RLRA  
Oyster Creek License Renewal Project Manager





