

RB Tendon/IWE/IWL Inspection:





Turbine Low Pressure Rotor Inspection:



RF-16 Emergent Activities

Failed Fuel:

- *Identified Assembly via In Mast Sipping and Visual Inspection*
- *Cause Determined to be Baffle Jetting*
- *Installed Clips to Prevent Recurrence*
- *Perform Upflow Modification in RF-18*



Upflow Conversion:

