



June 13, 2007  
L-2007-104  
10 CFR 50.90  
10 CFR 50.91

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555-0001

RE: Turkey Point Unit 3  
Docket No. 50-250  
Request to Withdraw  
License Amendment Request (LAR 192)  
Inoperable Rod Position Indication

By letter L-2007-083, dated May 17, 2007, "License Amendment Request (LAR 192) Inoperable Rod Position Indication," Florida Power and Light Company (FPL) requested exigent approval of changes to the Turkey Point Unit 3 Facility Operating License DPR-31, to allow the use of an alternate method of determining rod position for control rods M-6 and G-5 with inoperable Analog Rod Position Indicators (ARPIs). The ARPI for control rod M-6 in Control Bank C was declared inoperable in August 2006. The ARPI for control rod G-5 in Control Bank A was declared inoperable in April 2007.

Since the submittal of LAR 192, Turkey Point Unit 3 has experienced additional unexpected failures in the control rod ARPI system and has shutdown Unit 3 in accordance with station Technical Specifications. Turkey Point Unit 3 is currently shutdown in Mode 5 and is performing troubleshooting and repair activities on the ARPI system. As stated in FPL letter L-2007-083, Turkey Point will repair the inoperable ARPIs prior to restarting Unit 3; therefore, this letter documents FPL's request to withdraw LAR 192, since it is no longer needed.

If there are any questions, please contact James Connolly, Licensing Manager, at (305) 246-6632.

Very truly yours,

A large, stylized handwritten signature in black ink, appearing to read 'W. Jefferson, Jr.', is written over the typed name.

William Jefferson, Jr.  
Vice President  
Turkey Point Nuclear Plant

cc: Regional Administrator, Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant  
Mr. W. A. Passetti, Florida Department of Health

A001