

Closed Generic Communication TACs (PA No. 101122CA/B)
Summary Report (AS OF 06/30/2007)

TAC NO.	TAC TITLE	STATUS	AGE	TAC CLOSED	LEAD ORG
MD1658	RIS 2006-21 'Request for Licensee Information for Input into the NRC's Incident Response e-Library'	C	5.7	10/30/2006	NSIR
MD1211	RIS 'Generic Safety Issue 191 - Scheduler Considerations'	W	7.4	11/28/2006	DSS
MC9661	RIS 2006-24 'Revised Review and Transmittal Process for Accident Sequence Analyses'	C	10.6	12/15/2006	RES
MD2191	RIS 2006-23 'Ventilation and Air Conditioning Operability in Emergency Diesel Generator Rooms'	C	6.3	12/15/2006	DE
MD3251	RIS 2006-22 'Lessons Learned from Recent 10 CFR Part 72 Exemption Granted to the Ft. Calhoun Station'	C	3.3	1/24/2007	NMSS
MD3384	RIS 2007-01 'Clarification of NRC Guidance for Maintaining a Standard Emergency Action Level Scheme'	C	2.7	1/16/2007	NSIR
MD4015	RIS & Reg Analysis on Consideration of Fire Risk for 10 CFR 50.65(a)(4)	CAN	0	1/18/2007	PGCB
MD3532	RIS 2006-02 'Clarification of NRC Guidance for Emergency Notifications During Quickly Changing Events'	C	3.2	2/14/2007	NSIR
MD3577	RIS 2007-04 'Personally Identifiable Information Submitted to the NRC'	C	4.0	3/16/2007	OSI
MD4605	RIS 2007-06 'Regulatory Guide 1.200 Implementation'	C	0.9	3/26/2007	DRA
MD4606	RIS 2007-03 'Ionizing Warning Symbol'	C	0.6	3/16/2007	FSME
MD4643	RIS 2007-8 'Updated Licensing Submittal Info to Support the Design-Centered Licensing Review Approach'	C	1.5	4/17/2007	NRO
MD3788	RIS 2007-12 'Changes to the Unplanned SCRAMS with Loss of Normal Heat Removal Performance Indicator'	C	6.4	6/27/2007	DIRS
MD4208	RIS 2007-XX 'Recent Exper with Vendors who Supply Basic Compnts to NPP Related to Implem of 10CFRPart 21'	W	4.8	6/25/2007	DE

MD1710	IN 2006-24 'Recent Operating Experience on Safety/Relief Value Setpoint'	C	6.0	11/14/2006	DCI
MD1918	IN 2006-26 'Failure of Magnesium Rotor in Motor Operated Valve Actuators'	C	6.0	11/21/2006	R2
MD2564	IN 2006-28 'Siren System Failures Due To Erroneous Signal From One Siren'	C	5.9	12/28/2006	NSIR
MD2540	IN 2006-27 'Circumferential Cracking in Pressurizer Stainless Steel Heater Sleeve'	C	5.8	1/04/2007	DCI
MD3667	IN 2006-18 'Auxiliary Feedwater System Inop Due to Air/Debris from Backup Water Sources'	C	5.7	5/15/2007	DSS
MD3572	IN 2007-17 'Potential Fire Hazard w/Flame Retardant Spring Reinforced Polyethylene Film'	C	5.6	5/4/2007	DRA
MD3422	IN 2006-15 'Ethernet-Based Non-Safety Control System Causes Reactor Trip'	C	5.6	4/18/2007	DE
MD3005	IN 2007-06 'Potential Common Cause Vulnerabilities in Essential Service Water Systems'	C	4.9	2/15/2007	DIRS
MD3007	IN 2007-05 'Vertical Deep Draft Service Water Pump Shaft and Coupling Failures'	C	4.9	2/15/2007	DIRS
MD3999	IN 2007-21 'Flow-Indicated Vibration Could Cause Metal Insulation to Damage CVCS Piping'	C	4.9	6/14/2007	R2
MD3907	No IN Issued	C	4.9	6/25/2007	R1
MD3028	IN 2006-XX 'Fire Protection System Jockey Pump Recall' (No IN Issued)	C	4.8	2/12/2007	DRA
MD3651	IN 2007-14 'Catawba Loss of Offsite Power and Dual--Unit Trip'	C	4.6	4/10/2007	DE
MD4082	IN 2007-20 'Use of Blank Ammunition'	C	4.6	6/13/2007	NSIR
MD2101	IN 2006-13 'Contamination of Onsite Ground-Water Due to Leakage from Structures, Systems, ...'	C	4.4	10/13/2006	NMSS
MD3008	IN 2006-XX 'Implementation of 10 CFR Part 21 Based on Recent Experience at Vendor Facilities' (IN not being issued)	C	4.2	1/24/2007	DE
MD2455	IN 2006-14 'Potentially Defective Lead-Wire Connectors on Barton Pressure Transmitters'	C	3.9	10/25/2006	DE
MD2918	IN 2006-31 'Inadequate Fault Interrupting Rating of Breakers'	C	3.9	12/28/2006	DE
MD3842	IN 2007-09 'Inconsistency between Minimum Allowable Value of Degraded Voltage Settings'	C	3.9	4/17/2007	DIRS
MD3547	IN 96-69, Supp. 1, 'Operator Actions Affecting Reactivity' (Issued w/another IN)	C	3.7	3/6/2007	RIII
MD2966	IN 2006-29 'Motor-Operated Valve Failures from Stem Nut Wear as a Result of Inadequate Lubrication'	C	3.5	12/28/2006	DCI

MD3666	IN 2007-01 'Leaking Hydrostatic Barriers	C	3.2	2/26/2007	DIRS
MD3785	IN 2007-02 'Potential Failure of Control Rod Drive Mechanism Leadscrew Male Coupling'	C	3.1	3/16/2007	DIRS
MD4627	IN 2007-19 'Faulty Active Fire Protection Equipment'	C	3.0	5/29/2007	DRA
MD3908	IN 2007-11 '2006 Recent Operator Performance Issues	C	2.3	3/16/2007	DIRS
MD2834	IN 2006-20 'Foreign Material Found in Emergency Core Cooling System'	C	2.2	10/25/2006	DCI
MD3847	IN 2007-07 'Potential Failure of All Control Rods Groups to Insert in a BWR Due to a Fire'	C	2.0	2/20/2007	DRA
MD2967	IN 2006-14, Sup 1, 'Potentially Defective External Lead-Wire Conn. In Barton Pressure Trans.'	C	1.4	10/25/2006	DE
MD3650	IN 2006-30 'Summary of Fitness-For-Duty Program Performance Reports for Calendar Years 2004 and 2005'	C	1.2	12/28/2006	NSIR
MD3015	IN 2006-22 'Ultra Low Sulfur EDG Fuel Oil'	C	1.2	10/25/2006	DIRS
MD4446	IN 2007-08 'Vulnerabilities of Time Reliant Computer Based Systems Due to Change in DST Dates'	C	0.2	3/7/2007	DE
MD3546	IN 2006-25 'Lessons Learned from NRC Inspt of Control and Accounting of Special Nuclear Material' (SAFEGUARDS)	C	0.0	1/16/2007	NSIR
MC6496	GL 2007-01 'Inaccessible or Underground Cable Failures that Disable Accident Mitigation Systems'	C	22.6	2/14/2007	DE
MC6498	GL 2005-XX 'Post-Fire Safe-Shutdown Circuit Analysis Spurious Actuations'	W	20.6	12/15/2006	DRA
MD0557	BL 2006-XX 'Abnormal Liquid Effluent Releases and Ground-Water Contamination Due to ...'	W	10.3	1/30/2007	DIRS