

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority

License Nos. CPPR-91
CPPR-92

Based on the results of the NRC inspection conducted on December 1-22, 1978, it appears that certain of your activities were not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in our correspondence to you dated December 31, 1974.

Criterion III of Appendix B to 10 CFR 50, as implemented by paragraph 17.1A.3.1 of the FSAR, required, in part, that "Measures shall also be established for...review for suitability of application of...equipment...essential to the safety-related functions...". Paragraph 5.3.2 of the Westinghouse E Specification for Swing Check Valves states "The valve must be mounted in a horizontal pipe run with the bonnet above the valve body". This also appears as a note on the Westinghouse drawings.

Contrary to the above requirement, the inspector identified eight (8) swing check valves mounted in vertical pipe runs in the Chemical and Volume Control System Piping.

This is an infraction.

7904110423