

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority
Watts Bar Nuclear Plant

License No. CPPR-91

Based on the NRC inspection January 8-12, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

- A. As required by Criterion V of Appendix B to 10 CFR 50 and implemented by FSAR paragraph 17.1A.5, "Activities affecting quality shall be prescribed by documented instructions, procedures or drawings...and shall be accomplished in accordance with these instructions, procedures or drawings."

Contrary to the above, on December 1, 1978, an installed piping subassembly had different subassembly and manufacturer's serial numbers than specified by the applicable drawing. Subassembly 62-CVCS-46, sketch 2876-278, Serial No. 6509 was located where the drawing E2879-IC-22R1 indicated subassembly 62A-CVCS-40, sketch 2879-273, Serial No. 6503 should be. As the incorrectly installed subassembly was of the same material and configuration as the subassembly specified by drawing, the safety significance of this noncompliance is considered minimal.

This is a deficiency.

7903160020