

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority
Watts Bar Nuclear Plant

License Nos. CPPR-91
& CPPR-92

Based on the NRC inspection August 1 - September 7, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Criterion V of Appendix B to 10 CFR 50 and as implemented by FSAR paragraph 17.1A.5, "Activities affecting quality shall be prescribed by documented instructions, procedures...and shall be accomplished in accordance with these instructions, procedures...". Watts Bar Quality Control Procedure, WBNP-QCP-3.6 Rev. 6, paragraph 6.1.18 states, in part, that a device be used to verify that the maximum allowable pull tension is not exceeded.

Contrary to the above, on September 7, 1979, a dynamometer device was installed in the cable run to measure the pulling force on the cable. The dynamometer was installed in a manner in which it could not monitor the cable pulling force on the 4/1 (300 MCM) conductors being pulled.

This is an infraction.